

County Surveyor's Record, Douglas County, Oregon

18515

Subdivision of Section 19,
T. 29 S., R. 7 W., Willamette Meridian, Oregon

CHAINS	
70.910	<p>A fir, 17 ins. diam., bears S. 18 3/4° E., 235½ lks. dist. mkd. CN 1/16 S19 BT.</p> <p>A cedar, 14 ins. diam., bears S. 13° W., 163½ lks. dist., mkd. CN 1/16 S19 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>The ¼ sec. cor. of secs. 18 and 19.</p>
5.380	<p>From the ¼ sec. cor. of secs. 19 and 20.</p> <p>N. 80° 32' 30" W., on the E. and W. center line of sec. 19.</p> <p>Ascend over broken SE. slope, through heavy timber and moderate undergrowth.</p> <p>Intersect line 5-6 of the Oro Grande placer claim.</p>
9.830	<p>Point for the center E-E 1/64 sec. cor. of sec. 19.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 19 C-E-E 1/64 1988</p> <p>from which</p> <p>A fir, 13 ins. diam., bears N. 22° E., 28 lks. dist., mkd. X BT.</p> <p>A fir, 25 ins. diam., bears N. 85° W., 11½ lks. dist., mkd. CEE 1/64 S19 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
19.660	<p>Point for the center E 1/16 sec. cor. of sec. 19.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd</p> <p style="text-align: center;">C $\frac{E \ 1/16}{S \ 19}$ C 1988</p> <p>from which</p> <p>A fir, 9 ins. diam., bears N. 83° E., 45 lks. dist., mkd. X BT.</p> <p>A fir, 12 ins. diam., bears N. 64° W., 22 lks. dist., mkd. CE 1/16 S19 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
39.320	<p>The center ¼ sec. cor. of sec. 19.</p>
54.10	<p>Gravel road, 20 lks. wide, bears N. 30° E. and S. 30° W.</p>
55.40	<p>Spur, slopes N. 45° E.; desc. over broken NW. slope.</p>
60.480	<p>Point for the center W 1/16 sec. cor. of sec. 19.</p>