

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 19,
T. 29 S., R.7 W., Willamette Meridian, Oregon 18548

CHAINS	
23.20	Coarse Gold Creek, 10 lks. wide, course N. 50° E.; asc. over broken SE. slope.
28.680	<p>Point for the center N-SE 1/64 sec. cor. of sec. 19.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 19 C-N-SE 1/64 1989</p> <p>from which</p> <p style="padding-left: 40px;">A cedar, 21 ins. diam., bears S. 88° E., 47 lks. dist., mkd. CN SE 1/64 S19 BT.</p> <p style="padding-left: 40px;">A fir, 26 ins. diam., bears N. 39½° W., 61 lks. dist., mkd. CN SE 1/64 S19 Bt.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
38.245	<p>The center E 1/16 sec. cor. of sec. 19.</p> <hr/> <p>From the S 1/16 sec. cor. of secs. 19 and 20.</p> <p>N. 80° 29' 00" W., on the E. and W. center line of the SE¼ of sec. 19.</p> <p>Descend over broken NW. slope, through heavy timber and moderate undergrowth.</p>
17.00	Gravel road, 20 lks. wide, bears N. 50° E. and S. 40° W.
19.215	Intersect line 2-3 of the Oro Grande placer claim.
19.930	Intersect line 3-4 of the Oro Grande placer claim.
20.055	The SE 1/16 sec. cor. of sec. 19.
24.10	Coarse Gold Creek, 10 lks. wide, course N. 50° E.; asc. over broken SW. slope.
30.085	<p>Point for the center W-SE 1/64 sec. cor. of sec. 19.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 19 C-W-SE 1/64 1988</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears N. 4¼° E., 45 lks. dist., mkd. CW SE 1/64 S19 BT.</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears S. 62½° E., 37½ lks. dist., mkd. X BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p>
40.115	The center S 1/16 sec. cor. of sec. 19.