

County Surveyor's Record, Douglas County, Oregon

18565 Dependent Resurvey of a Portion of the North Boundary,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

from which the remains of the original bearing trees

A fir snag, 42 ins. diam., bears N. 72° E., 72 lks. dist., with old axe marks visible.

A rotted fir stump, 38 ins. diam., bears S. 25° E., 58 lks. dist., no marks visible. (Record, 62 lks.)

A rotted fir stump, 36 ins. diam., bears S. 4° W., 74½ lks. dist., no marks visible. (Record, 76 lks.)

The rotted remains of a fir stump, size indeterminate, bears N. 59° W., 76 lks. dist., no marks visible. (Record, 73 lks.)

and bearing trees mkd. by Ware

A fir, 12 ins. diam., bears N. 56½° E., 13 lks. dist., with healed blaze.

A fir, 19 ins. diam., bears S. 26° E., 7 lks. dist., with illegible scribe marks visible on partially healed blaze.

A fir, 13 ins. diam., bears S. 45° W., 20½ lks. dist., with illegible scribe marks visible on partially healed blaze.

A fir, 14 ins. diam., bears N. 60° W., 12½ lks. dist., with healed blaze.

Corrective Dependent Resurvey of a Portion of
the Subdivisional Lines,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

(Restoring the survey by William H. Byars, in 1881,
and correcting the resurvey by Rollin D. Aanrud, in 1966-67)

From the ¼ sec. cor. of secs. 10 and 15, monumented with an iron post, 2½ ins. diam., firmly set, projecting 7 ins. above ground, with brass cap mkd.

T 32 S R 6 W
¼ $\frac{S 10}{S 15}$
1966

from which the remains of the original bearing trees

A fir, 45 ins. diam., bears S. 2° E., 46 lks. dist., with scribe marks ¼ BT visible on bark blaze.

A rotted fir stump, size indeterminate, bears N. 15° W., 24 lks. dist., with a down fir, 40 ins. diam., lying alongside, with healed blaze. (Record, 22 lks.)

and bearing trees mkd. by Aanrud

A fir, 22 ins. diam., bears N. 7½° E., 79 lks. dist., with healed blaze. (Record, N. 3° E., 81 lks.)

A fir, 21 ins. diam., bears S. 78½° E., 86 lks. dist., with healed blaze. (Record, S. 88½° E.)

S. 89° 06' 00" W., bet. secs. 10 and 15.

Descend across a broken SW. slope, through timber.