

County Surveyor's Record, Douglas County, Oregon

18571 Dependent Resurvey of a Portion of the Subdivisional Lines,
 T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS

The corner is located at the SE. cor. of timber, edge bears N. and W.

N. 2° 22' 30" E., beginning new measurement

Descend along E. slope following W. edge of timber.

9.20 Creek, 2 lks. wide, course SE.; asc. S. slope.

19.890 The $\frac{1}{4}$ sec. cor. of secs. 10 and 11, monumented with an iron post, $1\frac{1}{2}$ ins. diam., firmly set, projecting 14 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

BLM
 S | S
 $\frac{1}{4}$ 10 | 11
 T 32 S R 6 W
 1966
 1959

from which the remains of the original bearing trees

A fir snag, 22 ins. diam., bears S. 70° E., 16 lks. dist., with scribe marks BT visible on a partially healed and burned blaze.

A fir stump, 48 ins. diam., bears N. 10° W., 34 lks. dist., no marks visible. (Record, 31 lks.)

and bearing trees mkd. by James W. Byron, Douglas County Deputy Surveyor, in 1959

A cedar, 18 ins. diam., bears S. 54° E., 57 lks. dist., with illegible scribe marks visible on a partially healed blaze. (Record, S. 52° E., 56 lks.)

A fir, 15 ins. diam., bears S. 85° W., 42 lks. dist., with healed blaze. (Record, S. 86° W., 41 lks.)

From the cor. of secs. 2, 3, 10, and 11, monumented with an iron post, $1\frac{1}{2}$ ins. diam., firmly set, projecting 16 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

S 3 | S 2
 S 10 | S 11
 T 32 S R 6 W
 1959

from which the remains of the original bearing trees

A rotted fir stump, size indeterminate, bears N. 35° E., 19 lks. dist., no marks visible.

A fir, 47 ins. diam., bears S. 65° E., 28 lks. dist., with healed blaze.

A fir stump, 38 ins. diam., bears S. 60° W., 9 lks. dist., with healed blaze.

and remains of bearing trees mkd. by James W. Byron, Douglas County Deputy Surveyor, in 1959

A fir snag, 15 ins. diam., bears N. 36° E., 133 lks. dist., with healed blaze. (Record, N. 37° E., 134 lks.)