

County Surveyor's Record, Douglas County, Oregon

18585

Subdivision of Section 10,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	<p>Ascend SW. slope, through heavy timber and undergrowth.</p> <p>1.00 Creek, 1 lk. wide, course S. 50° W.</p> <p>12.70 Spur, slopes S. 60° W.; desc. NW. slope.</p> <p>19.790 Point for the SW 1/16 sec. cor. of sec. 10, at intersection with the E. and W. center line of the SW¼.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">SW 1/16 S 10 1986</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 6 ins. diam., bears N. 51½° E., 44 lks. dist., mkd. X BT.</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears S. 12° E., 44½ lks. dist., mkd. SW 1/16 S10 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.</p> <p>Across a broken S. slope, through timber.</p> <p>39.560 The center W 1/16 sec. cor. of sec. 10.</p>
	<p>From the center S 1/16 sec. cor. of sec. 10.</p> <p>S. 89° 32' 00" W., on the E. and W. center line of the SW¼ of sec. 10.</p> <p>Across a broken NW. slope, through heavy timber and dense undergrowth.</p> <p>20.005 The SW 1/16 sec. cor. of sec. 10.</p> <p>Continue across broken NW. slope, changing to SW.</p> <p>40.000 The S 1/16 sec. cor. of secs. 9 and 10.</p>
	<p>Subdivision of Section 14, T. 32 S., R. 6 W., Willamette Meridian, Oregon</p>
	<p>From the ¼ sec. cor. of secs. 14 and 23.</p> <p>N. 0° 39' 00" E., on the N. and S. center line of sec. 14.</p> <p>Ascend across E. slope, through timber and dense undergrowth.</p> <p>14.00 Begin descent along E. slope.</p> <p>19.660 Point for the center S 1/16 sec. cor. of sec. 14.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">C S 1/16 S 14 C 1986</p> <p>from which</p>