

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the South Boundary,  
T. 21 S., R. 4 W., Willamette Meridian, Oregon

18602

CHAINS										
	<p>A fir, 34 ins. diam., bears S. 20 3/4° W., 93 lks. dist., with healed blaze.</p> <p>A fir, 37 ins. diam., bears N. 10° W., 79 lks. dist., with healed blaze.</p>									
	<p>Dependent Resurvey of a Portion of the West Boundary, T. 21 S., R. 4 W., Willamette Meridian, Oregon</p>									
	<p>(Restoring the survey by Harvey Gordon and Charles T. Gardner in 1855-56)</p>									
	<p>From the cor. of Tps. 21 and 22 S., Rs. 4 and 5 W. N. 0° 41' 30" W., bet. secs. 31 and 36. Descend over broken NW. slope, changing to NE. slope, through heavy timber and dense undergrowth.</p>									
18.55	Creek, 3 lks. wide, course N. 40° W.; asc. over SW. slope.									
19.950	<p>The S 1/16 sec. cor. of secs. 31 and 35, established and recorded by H. McGillicuddy, Registered Engineer No. 2066, in 1953, and is accepted as the corner; monumented with an iron pipe, 3/4 in. diam., firmly set, projecting 4 ins. above ground, from which the remains of bearing trees mkd. by McGillicuddy:</p> <p style="padding-left: 40px;">A root hole, bears S. 28 1/2° E., 32 lks. dist., with a down fir alongside, 24 ins. diam., with healed blaze.</p> <p style="padding-left: 40px;">A sawed fir stump, 19 ins. diam., bears N. 35 1/4° W., 15 lks. dist., with fragmentary scribe marks visible on opened blaze.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto;"> <tr><td></td><td>S 1/16</td><td></td></tr> <tr><td>S 36</td><td> </td><td>S 31</td></tr> <tr><td></td><td>1988</td><td></td></tr> </table> </div> <p>from which new bearing trees</p> <p style="padding-left: 40px;">A fir, 22 ins. diam., bears S. 74 1/2° E., 51 lks. dist., mkd. S 1/16 S31 BT.</p> <p style="padding-left: 40px;">A hemlock, 9 ins. diam., bears N. 5° W., 58 lks. dist., mkd. S 1/16 S36 BT.</p> <p>Deposit iron pipe alongside and white "DEEP-1" magnetic marker at base of stainless steel post.</p>		S 1/16		S 36		S 31		1988	
	S 1/16									
S 36		S 31								
	1988									
	<p>N. 0° 44' 30" W., beginning new measurement. Ascend over SW. slope.</p>									
4.25	Spur, slopes N. 30° W.; desc. over broken NE. slope.									
14.15	Gravelled road, 25 lks. wide, bears N. 30° E. and S. 30° W.									
16.90	Creek, 4 lks. wide, course NW.; asc. over SW. slope.									
19.940	The 1/4 sec. cor. of secs. 31 and 36, reestablished and recorded by									