

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,
 T. 21 S., R. 4 W., Willamette Meridian, Oregon
18605

CHAINS									
	At the corner point Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.								
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="2">T 21 S R 4 W</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 2px 5px;">S 30</td> <td style="padding: 2px 5px;">S 29</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 2px 5px;">S 31</td> <td style="padding: 2px 5px;">S 32</td> </tr> <tr> <td colspan="2" style="padding: 2px 5px;">1988</td> </tr> </table>	T 21 S R 4 W		S 30	S 29	S 31	S 32	1988	
T 21 S R 4 W									
S 30	S 29								
S 31	S 32								
1988									
	from which								
	<p style="margin-left: 40px;">A maple, 21 ins. diam., bears N. 78° E., 66 lks. dist., mkd. T21S R4W S29 BT.</p> <p style="margin-left: 40px;">A fir, 11 ins. diam., bears S. 3½° E. 98 lks. dist., mkd. X BT.</p> <p style="margin-left: 40px;">A maple, 25 ins. diam., bears N. 78½° W., 100 lks. dist., mkd. T21S R4W S30 BT.</p>								
	Deposit the iron pipe and iron rod inside and white "DEEP-1" magnetic marker at base of stainless steel post.								
	S. 88° 53' 30" W., bet. secs. 30 and 31.								
	Descend over W. slope through open land.								
4.55	Buck Creek, 30 lks. wide, course SW.; cont. over creek bottom.								
5.05	Buck Creek, 30 lks. wide, course N. 5° E.; asc. over broken NE. slope.								
7.15	Douglas County Road No. 61, asphalt surface, 45 lks. wide, bears N. 80° W., S. 50° E., and S., in junction.								
16.65	Creek, 2 lks. wide, course N. 55° W.; asc. over broken NE. slope.								
16.85	Road, asphalt surface, 45 lks. wide, bears N. 65° E. and S. 55° W.								
18.25	Center line, northbound lanes, Interstate Route 5, 60 lks. wide, bears N. 80° W. and S. 75° E.								
23.50	Center line, southbound lanes, Interstate Route 5, 60 lks. wide, bears N. 75° W. and S. 75° E.								
26.00	Power service line, 2 wire, bears W. and S. 70° E.								
27.05	Douglas County Road No. 61, asphalt surface, 45 lks. wide, bears N. 80° W. and S. 75° E.								
35.85	Dirt road, 25 lks. wide, bears N. 70° W. and S. 70° E.								
40.400	Point for the ¼ sec. cor. of secs. 30 and 31, at proportionate distance; there is no remaining evidence of the original corner. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.								
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="2">T 21 S R 4 W</td> </tr> <tr> <td colspan="2" style="padding: 2px 5px;">¼ S 30</td> </tr> <tr> <td colspan="2" style="padding: 2px 5px;">S 31</td> </tr> <tr> <td colspan="2" style="padding: 2px 5px;">1988</td> </tr> </table>	T 21 S R 4 W		¼ S 30		S 31		1988	
T 21 S R 4 W									
¼ S 30									
S 31									
1988									
	from which								
	<p style="margin-left: 40px;">A fir, 10 ins. diam., bears S. 58 ¾° E., 54 lks. dist., mkd. ¼ S31 BT.</p> <p style="margin-left: 40px;">A fir, 10 ins. diam., bears N. 24° W., 129 lks. dist., mkd. ¼ S30 BT.</p>								