

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 21 S., R. 4 W., Willamette Meridian, Oregon 18610

CHAINS

from which the remains of an original bearing tree

A cedar snag, 20 ins. diam., bears S. 48° E., 30 lks. dist., with fragmentary scribe marks visible on an opened blaze. (Record, redwood.)

and bearing tree mkd. by Tracy

A hemlock, 14 ins. diam., bears S. 17½° E., 13½ lks. dist., with healed double blaze.

A hemlock, 13 ins. diam., bears S. 22¼° W., 22 lks. dist., with healed double blaze.

Subdivision of Section 17,
T. 21 S., R. 4 W., Willamette Meridian, Oregon

From the ¼ sec. cor. of secs. 17 and 20.

N. 0° 08' 30" W., on the N. and S. center line of sec. 17.

Descend over N. slope, through light timber and dense undergrowth.

0.20 Pass Creek, 35 lks. wide, course N. 60° W.; asc. over broken SE. slope.

5.35 Gravelled road, 25 lks. wide, bears SE. and N. 55° W.

20.120 Point for the center S 1/16 sec. cor. of sec. 17.

Set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} C \\ S\ 1/16 \left| \right. S\ 17 \\ C \\ 1989 \end{array}$$

from which

A fir, 6 ins. diam., bears S. 76¼° E., 82 lks. dist., mkd. X BT.

A fir, 11 ins. diam., bears S. 64 ¾° W., 45 lks. dist., mkd. CS 1/16 S17 BT.

Ascend over SE. slope.

28.70 Ridge, bears N. 5° W. and S. 30° W.; asc. along top of ridge.

37.25 Leave ridge; desc. over NE. slope.

40.240 Point for the center ¼ sec. cor. of sec. 17, at intersection with the E. and W. center line.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

$$\begin{array}{c} T\ 21\ S\ R\ 4\ W \\ C\ 1/4\ S17 \\ 1988 \end{array}$$

from which

A fir, 11 ins. diam., bears N. 29° E., 28 lks. dist., mkd. C¼ S17 BT.

A fir, 33 ins. diam., bears S. 67° W., 52 lks. dist., mkd. C¼ S17 BT.