

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 22 S., R. 4 W., Willamette Meridian, Oregon 18622

CHAINS

A root hole, bears S. 77° W., 22 lks. dist., with a down fir alongside, size indeterminate, no marks visible.

A fir snag, 36 ins. diam., bears N. 47° W., 18 lks. dist., with fragmentary scribe marks visible on opened blaze.

and the remains of a bearing tree mkd. by Martin

A sawed fir stump, 21 ins. diam., bears N. 75° E., 32 lks. dist., with scribe marks 22S R4W S14 visible on partially healed blaze.

and the bearing trees mkd. by Godfrey

A fir, 31 ins. diam., bears N. 42° W., 133 lks. dist., with healed double blaze.

A fir, 18 ins. diam., bears S. 68° W., 76 lks. dist., with healed double blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron pipe and T iron, with brass cap mkd.

T 22 S R 4 W	
S 15	S 14
S 22	S 23
1988	

from which new bearing trees

A fir, 10 ins. diam., bears N. 54½° E., 8 lks. mkd. T22S R4W S14 BT.

A fir, 11 ins. diam., bears S. 23° E., 21 lks. dist., mkd. T22S R4W S23 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

N. 88° 52' 00" W., bet. secs. 15 and 22, marking and blazing the true line.

Descend over broken NW. slope, through heavy timber and dense undergrowth.

18.45 Creek, 12 lks. wide, course N. 10° W.; asc. over NE slope.

19.95 Spur, slopes N. 15° E.; desc. over NW. slope.

20.80 Ravine, drains N. 5° W.; asc. over NE. slope.

24.70 Spur, slopes N. 40° E.; desc. over broken NW. slope.

28.80 Ravine, drains N. 15° W.; asc. over broken NE. slope.

37.35 Spur, slopes N. 10° W.; desc. over broken NW. slope.

38.400 Point for the ¼ sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28" ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S R 4 W	
S 15	
¼	S 22
1988	

from which