

County Surveyor's Record, Douglas County, Oregon

18636

Subdivision of Section 10,
T. 30 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	<p>in the ground, with brass cap mkd. <div style="text-align: center;">T 30 S. R 6 W C$\frac{1}{4}$ S 10 1988</div> </p>
	<p>from which</p> <p style="padding-left: 40px;">A Pine, 8 ins. diam., bears S. 39° W., 14 lks. dist., mkd. X at breast height and BT at the base.</p> <p style="padding-left: 40px;">A pine, 11 ins. diam., bears N. 63$\frac{1}{2}$° W., 21$\frac{1}{2}$ lks. dist., mkd. C$\frac{1}{4}$ S10 BT.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p> <p>Descend over NW. slope.</p>
42.10	Head of ravine, drains S. 55° W.; asc. over SE. slope.
71.50	Ridge bears N. 75° E. and S. 75° W.; desc. over NW. slope.
79.470	The $\frac{1}{4}$ sec. cor. of secs. 3 and 10, monumented with an iron post, 1 $\frac{1}{4}$ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.
	<p>COUNTY SURVEYORS OFFICE</p> <div style="text-align: center;">S 3 $\frac{1}{4}$ S 10 1963</div>
	<p>from which the remains of an original bearing tree</p> <p style="padding-left: 40px;">A root hole, bears S. 30° W., 5 lks. dist., with down fir alongside, size indeterminate, no marks visible.</p> <p>and the remains of bearing trees mkd. by John H. Markham, Jr., Registered Engineer No. 2880, in 1957.</p> <p style="padding-left: 40px;">A broken fir stump, size indeterminate, bears N. 36° E., 57$\frac{1}{2}$ lks. dist., no marks visible.</p> <p style="padding-left: 40px;">A sawed fir stump, 26 ins. diam., bears N. 63° E., 54 lks. dist., with scribe marks BT visible on opened blaze.</p> <p style="padding-left: 40px;">A sawed fir stump, 37 ins. diam., bears N. 13° W., 51 lks. dist., with healed blaze.</p> <p>and a bearing tree mkd. by Roseberry</p> <p style="padding-left: 40px;">A cedar, 11 ins. diam., bears N. 73° W., 61 lks. dist., with healed double blaze.</p> <p>and a new bearing tree</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S. 60° E., 6$\frac{1}{2}$ lks. dist., mkd. $\frac{1}{4}$ S10 BT.</p>
	<hr/> <p>From the $\frac{1}{4}$ sec. cor. of secs. 10 and 11, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1963, monumented with an iron post, 1$\frac{1}{4}$ ins. diam., firmly set, projecting 12 ins. above ground, with brass cap incorrectly mkd.</p>
	<p>COUNTY SURVEYORS OFFICE</p> <div style="text-align: center;">T 30 S $\frac{1}{4}$ S 12 S 11 R 6 W 1963</div>
	<p>from which the remaining original bearing trees</p>