

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 15,
T. 30 S., R. 6 W., Willamette Meridian, Oregon **18642**

CHAINS

From this point, an Oregon State Highway Department bench mark, used as Horizontal control Station 3057 at latitude 42° 58' 24.385" N. and longitude 123° 20' 39.630" W., by the Douglas County Surveyor's Office in 1982, bears N. 81° 11' 30" E., 229.405 chs. dist., monumented with a brass tablet, 3 ins. diam., set flush in the S. curb, 4 ft. from E. end of bridge across the South Umpqua River, with top mkd. OREGON STATE HIGHWAY DEPT DCSO 3057.

Descend over NE. slope.

36.70 Lane Creek, 5 lks. wide, course S. 80° E.; asc. along creek bottom.

38.10 Lane Creek, 5 lks. wide, course S. 30° W. from N. 30° W.; asc. over SW. slope.

40.105 The W. 1/16 sec. cor. of secs. 10 and 15.

From the center N 1/16 sec. cor. of sec. 15.

N. 89° 19' 30" W., on the E. and W. center line of the NW¼ of sec. 15.

Ascend over NE. slope, through heavy timber and dense undergrowth.

20.275 The NW 1/16 sec. cor. of sec. 15.

Ascend over NE. slope.

22.05 Dirt road, 20 lks. wide, bears N. 40° W. and S. 40° E.

26.90 Ridge, bears N. 20° W., to saddle, and S. 20° E.; desc. over SW. slope.

35.80 Head of ravine, drains S. 20° E.; asc. over SE. slope.

40.570 The N 1/16 sec. cor. of secs. 15 and 16, monumented with an iron post, 2½ ins. diam., firmly set, projecting 2 ins. above ground with brass cap mkd.

N 1/16
S 16 | S 15
1967

from which bearing trees mkd. by Roseberry

A fir, 22 ins. diam., bears N. 60½° E., 134½ lks. dist., with healed blaze.

A fir, 23 ins. diam., bears N. 31° W., 101 lks. dist., with healed blaze.

GENERAL DESCRIPTION

The lands included in the foregoing survey are located in mountainous country in Douglas County, about two miles north-westerly of Riddle, Oregon. The elevation ranges from about 1600 feet above sea level at the ¼ section corner of sections 14 and 15, to about 2440 feet above sea level near the ¼ section corner of sections 3 and 10.

The area is drained by Judd Creek, Sanderson Creek, Lane Creek, Jerry Creek, and other small and seasonal drainages flowing southeasterly to Cow Creek. The soil consists of rocky clay.

Timber is made up of fir, cedar, pine, yew, maple, ash, madrone, oak, chinquapin, alder, and dogwood. The undergrowth is mainly manzanita, poison oak, salal, Oregon grape, arrowwood, blackberry, azalea, huckleberry, wild rose, vine maple, ferns, thimbleberry, and young timber.