

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

18656

CHAINS

A root hole, bears N. 80° W., 55 lks. dist.,
with down yew alongside, 7 ins. diam., tree
is buried, no marks found.

At the corner point

Reset iron post, 1½ ins. diam., 30 ins. long, 24 ins. in
ground, with brass cap incorrectly mkd.

COUNTY SURVEYORS OFFICE

T 25 S

¼ S 13 | S 14

R 1 W

1966

and a new bearing tree

A fir, 4 ins. diam., bears N. 16½° W., 46 lks. dist.,
mkd. ¼ S14 BT.

N. 0° 21' 00" E., bet. secs. 13 and 14.

Ascend over SW. slope, through scattering timber and dense
undergrowth.

1.80 Spur, slopes, N. 80° W.; desc. over broken NW. slope.

19.25 Creek, 5 lks. wide, course S. 70° W.; asc. over broken SW. slope.

20.230 The N 1/16 sec. cor. of secs. 13 and 14, established by person(s)
unknown, and is accepted as the corner; monumneted with an iron
pipe, 1 in. diam., firmly set, projecting 12 ins. above ground.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., directly
over the iron pipe, 24 ins. in the ground, with brass cap mkd.

N 1/16
S 14 | S 13
1988

from which

A fir, 11 ins. diam., bears N. 23° E., 9½ lks. dist.,
mkd. N 1/16 S13 BT.

A fir, 4 ins. diam., bears S. 70° W., 18½ lks. dist.,
mkd. X BT.

Deposit a white "DEEP-1" magnetic marker at base of stainless
steel post.

The corner is located at corner of logged area, edge bears N.
and W., timber to NW.

N. 0° 14' 30" E., beginning new measurement.

Ascend over broken SW. slope.

20.230 The cor. of secs. 11, 12, 13, and 14, perpetuated and recorded
by G. Robert Lecklider, Professional Engineer No. 4079, in 1960,
and further perpetuated and recorded by Vernon R. Tracy, Deputy
County Surveyor, in 1966; monumented with an iron post, 1½ ins.
diam., firmly set, projecting 12 ins. above ground, with brass
cap mkd.