

County Surveyor's Record, Douglas County, Oregon

18663 Subdivision of Section 14,
T. 25 S., R. 1 W., Willamette Meridian, Oregon

CHAINS	
	A fir, 17 ins. diam., bears N. 19° W., 25 lks. dist., mkd. NE 1/16 S14 BT.
	Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.
	Ascend over SW. slope.
35.20	Spur, slopes S. 70° W.; desc. over NW. slope.
37.75	Gravelled road, 15 lks. wide, bears N. 30° E. and S. 30° W.
40.450	The E 1/16 sec. cor. of secs. 11 and 14.
<hr/>	
	From the N 1/16 sec. cor. of secs. 13 and 14.
	S. 89° 42' 00" W., on the E. and W. center line of the NE¼ of sec. 14.
	Descend over SW. slope, through heavy timber and dense undergrowth.
0.75	Creek, 3 lks. wide, course S.; asc. over SE. slope.
3.10	Spur, slopes S.; desc. over broken SW. slope.
18.35	Creek, 1 lk. wide, course SW.; asc. over SE. slope.
19.10	Spur, slopes S. 60° W.; desc. over SW. slope.
20.155	The NE 1/16 sec. cor. of sec. 14.
	Descend over SW. slope. changing to NW. slope.
29.45	Gravelled road, 15 lks. wide, bears N. 10° W. and S. 10° E.
30.75	Same road, 15 lks. wide, bears N. 50° E. and N. 60° W., in a curve.
36.00	Canton Creek Road, paved, 30 lks. wide, bears N. 10° E. and S. 10° W.
40.285	The center N 1/16 sec. cor. of sec. 14.
<hr/>	
GENERAL DESCRIPTION	
<p>The lands included in the foregoing resurvey are located in Douglas County about 18 miles northeasterly of Glide, Oregon. The elevation ranges from about 1440 feet above sea level at the ¼ section corner of sections 14 and 22, (23?) to approximately 2800 feet above sea level at the corner of sections 11, 12, 13, and 14.</p> <p>The area is drained by Canton Creek, Camp Creek, and numerous other small and seasonal drainages. The soil consists of a rocky clay. The timber consists of fir, yew, cedar, hemlock, madrone, maple, alder, chinquapin, ash, and dogwood. The undergrowth is mainly rhododendron, poison oak, Oregon grape, hazel, manzanita, arrowwood, blackberry, thimbleberry, salmonberry, huckleberry, wild rose, vine maple, ferns and young timber.</p> <p>Access is gained via an oiled road along Canton Creek, with several gravelled and dirt roads branching from it into the area.</p> <p>No mineral deposits were noted along the lines resurveyed. The lands are used primarily for timber.</p> <p>The average of a number of readings in the area gives a value of 18½° E. for the mean magnetic declination. There is a range of approximately ¼° due to local attraction.</p>	