

County Surveyor's Record, Douglas County, Oregon

18671

Dependent Resurvey of a Portion of the West Boundary,
T. 29 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A sawed fir stump, 34 ins. diam., bears S. 33° E.,
33 lks. dist., no marks visible on opened blaze.

A sawed fir stump, 52 ins. diam., bears N. 42° W.,
9 lks. dist., with scribe marks † C on bark blaze.

and the remains of bearing trees mkd. by James W. Byron, Deputy
County Surveyor, in 1958, as recorded in Douglas County Surveyors
Office Corner Renewal File, T. 29 S., R.8 W., No. 52

A grand fir stump, 30 ins. diam., bears N. 9° E., 48 lks.
dist., with tree lying alongside, with healed double blaze.

A grand fir, 16 ins. diam., bears S. 26½° W., 20 lks. dist.,
with healed double blaze.

N. 0° 07' 30" W., bet. secs. 31 and 36, marking and blazing the
true line.

Descend over broken NE. slope, through heavy timber and dense
undergrowth.

0.85 Graveled road, 15 lks. wide, bears N. 85° W. and S. 85° E.

19.475 From this point, a local corner established and recorded by G.G.
Stewart, Deputy County Surveyor, in 1922, bears West, 0.105 chs.
dist., monumented with an iron pipe 1½ ins. diam., firmly set, 2
ins. below ground surface, as recorded in Douglas County Surveyor
Office Field Book No. 3, page 121. This corner was erroneously
positioned and was not utilized in this survey.

19.780 From this point, a local corner established and recorded by Ben B.
Irving, Deputy County Surveyor, in 1930, bears East, 0.030 chs.
dist., monumented with an iron rod, 1 in. diam., firmly set flush
with the ground, in a fence corner with fences extending N. and W.,
as recorded in Douglas County Surveyors Office Map File No. 4/59.
This corner was set by improper methods and was not utilized in
this survey.

20.285 The N 1/16 sec. cor. of secs. 31 and 36, monumented with an iron
post, 2½ ins. diam., firmly set, projecting 4 ins. above ground,
with brass cap mkd.

N 1/16
S 36 | S 31
1965

from which bearing trees mkd. by Beck

A fir, 28 ins. diam., bears N. 53° E., 64 lks. dist.,
with healed blaze.

A fir, 29 ins. diam., bears N. 59° W., 22 lks. dist.,
with healed blaze.

N. 0° 09' 00" W., beginning new measurement.

Descend over NE. slope.

1.20 Mill Creek, 10 lks. wide, course N. 60° W.; asc. over SW. slope.

4.655 Intersect a local corner established and recorded by Harold L. Ball,
Registered Engineer No. 6025, in 1976, monumented with an iron rod,
5/8 in. diam., firmly set, projecting 3 ins. above ground in a
fence corner with fences extending S. and W., as recorded in Douglas
County Surveyors Office Map File No. 59/6. This corner was not
utilized in this survey.

5.25 Spur, slopes N. 60° W.; desc. over nearly level land.