

County Surveyor's Record, Douglas County, Oregon

18682

Dependent Resurvey of a Portion of the Subdivision Lines,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

and the bearing trees mkd. by James W. Byron, Deputy County Surveyor, in 1961

A burnt hemlock, 15 ins. diam., bears S. 76° E.,
58 lks. dist., with healed blaze.

A burnt cedar, 15 ins. diam., bears S. 18½° W.,
59 lks. dist., with healed blaze.

A burnt maple, 14 ins. diam., bears N. 55° W.,
15 lks. dist., with healed blaze.

The cor. is 25 lks. N. of a creek, 10 lks. wide, course E.
S. 89° 44' 00" W., bet. secs. 11 and 14.

Ascend over SE. slope, through a recent burned area with
scattering, burnt timber.

- 5.40 Spur, slopes S. 40° E.; desc. over SW. slope.
- 10.20 Ravine, drains S. 50° E.; asc. over broken SE. slope.
- 20.70 Ridge, bears N. 20° W. and S. 20° E.; desc. over broken W. slope.
- 21.00 Dirt road, 15 lks. wide, bears N. 20° W. and S. 20° E.
- 38.980 Point for the ¼ sec. cor. of secs. 11 and 14, at proportionate
distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 20 ins.
in the ground, with brass cap mkd.

T 28 S R 4 W
¼ S 11
 S 14
 1987 ✓

from which

A yew, 8 ins. diam., bears S. 10° W., 42 lks. dist.,
mkd. ¼ S14 BT.

A cedar 15 ins. diam., bears N. 67° W., 18½ lks. dist.,
mkd. ¼ S11 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

Descend over NW. slope.

- 43.40 Lee Creek, 5 lks. wide, course S. 15° W.; asc. over broken E.
slope.
- 45.40 Graveled road, 20 lks. wide, bears N. 20° E. and S. 20° W.
Leave burnt area; enter scattering timber and dense undergrowth.
- 58.470 Point for the W 1/16 sec. cor. of secs. 11 and 14.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 26 ins.
in the ground, with brass cap mkd.

W 1/16 S 11
 S 14
 1987

from which

A fir, 11 ins. diam., bears S. 1¾° W., 12½ lks. dist.,
mkd. W 1/16 S14 BT.