

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Boundaries
of Mineral Survey No. 979,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

18685

CHAINS

MS
C 3
ES S 15
C 4
T 28 S R 4 W
1991

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Subdivision of Section 14,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

From the $\frac{1}{4}$ sec. cor. of secs. 14 and 23, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.

T 28 S R 4 W
 $\frac{1}{4}$ S 14
S 23
1963

from which the remains of bearing trees mkd. by Jelley

A cedar, 13 ins. diam., bears S. $0\frac{1}{2}^{\circ}$ E., 43 lks. dist., with healed blaze.

A burnt cedar root crown, size indeterminate, bears N. 40° W., 72 lks. dist.

and a new bearing tree

A fir, 7 ins. diam., bears N. $12\frac{1}{4}^{\circ}$ E., 36 lks. dist., mkd. $\frac{1}{4}$ S14 BT.

The corner is at the NE. cor. of a clearcut logging area.

N. $0^{\circ} 13' 00''$ W., on the N. and S. center line of sec. 14.

Descend over NE. slope, through a recent burned area with scattering burnt timber.

5.10 Creek, 2 lks. wide, course S. 10° E.; asc. over SW. slope.

36.10 Dirt road, 20 lks. wide, on ridge, bears E. and W.; desc. over NW. slope.

39.220 Point for the center $\frac{1}{4}$ sec. cor. of sec. 14, at intersection with the E. and W. center line.

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

T 28 S R 4 W
C $\frac{1}{4}$
S 14
1987

from which

A fir, 58 ins. diam., bears S. 45° E., 30 lks. dist., mkd. C $\frac{1}{4}$ S14 BT.

A fir, 6 ins. diam., bears N. 30° W., 31 lks. dist., mkd. C $\frac{1}{4}$ S14 BT.

Continue over broken NW. slope.