

County Surveyor's Record, Douglas County, Oregon

18690

Dependent Resurvey of a Portion of the South Boundary,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

CHAINS

diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE

T 28 S R 5 W

S 35|36

2|1

T 29 S R 5 W

1957

from which the remains of the bearing trees mkd. by Byron

A madrone, 8 ins. diam., bears N. 46 $\frac{1}{2}$ ° E., 37 lks. dist., with healed blaze.

A sawed fir stump, 55 ins. diam., bears S. 25° E., 109 lks. dist., no visible marks.

A madrone, 10 ins. diam., bears S. 8° W., 87 lks. dist., with healed double blaze.

A fir stump, 13 ins. diam., bears N. 19 $\frac{1}{2}$ ° W., 33 $\frac{1}{2}$ lks. dist., with healed double blaze.

and new bearing trees

A fir, 13 ins. diam., bears S. 17° E., 42 lks. dist., mkd. T29S R5W S1 BT.

A fir, 20 ins. diam., bears N. 9 $\frac{1}{2}$ ° W., 58 lks. dist., mkd. T28S R5W S35 BT.

The corner is located on the SE. side of the corner post of barbed wire fences extending N. and W., and a woven wire fence extending E.

S. 89° 32' 30" W., bet. secs. 2 and 35, marking and blazing the true line.

Descend over a broken SW. slope, through heavy timber and dense undergrowth.

15.80 Creek, 10 lks wide, course S.; asc. over steep NE. slope.

19.960 Point for the E 1/16 sec. cor. of secs. 2 and 35.

Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.

E 1/16 S 35
S 2
1988

from which

A fir, 5 ins. diam., bears S. 8° W., 8 $\frac{1}{2}$ lks. dist., mkd. X BT.

A fir, 19 ins. diam., bears N. 73° W., 33 lks. dist., mkd. E 1/16 S35 BT.

The corner is located on top of a spur, slopes N. 30° E.

Descend over NW. slope.

21.90 Creek, 3 lks. wide, course N. 60° E.; asc. over broken NE. slope.

32.70 Spur, slopes N.; desc. over NW. slope.

34.30 Creek, 3 lks. wide, course N. 60° E.; asc. over broken SE. slope.