

# County Surveyor's Record, Douglas County, Oregon

18692

Dependent Resurvey of a Portion of the South Boundary,  
T. 28 S., R. 5 W., Willamette Meridian, Oregon

CHAINS							
	<p>A pine, 16 ins. diam., bears S. 65½ E., 148 lks. dist., mkd. T29S R5W S2 BT.</p> <p>An X chiseled in the NE. face of a small rock outcrop, 2 x 3 x 1½ ft. above ground, bears S. 58° W., 9 lks. dist.</p> <p>A pine, 30 ins. diam., bears N. 56½° W., 125 lks. dist., mkd. T28S R5W S34 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>From this point, a point of unknown origin, bears S. 14° 25' W., 0.290 chs. dist., monumented with an iron pipe, 1½ ins. diam., loosely set, projecting 18 ins. above the ground.</p> <hr/> <p>S. 89° 32' 30" W., bet. secs. 3 and 34.</p> <p>Ascend over SE. slope, through scattering timber and undergrowth.</p>						
5.80	Spur, slopes S.; desc. over broken SW. slope.						
6.10	Dirt road, 20 lks. wide, bears N. 10° W. and S. 10° E.						
17.10	Creek, 2 lks. wide, course S.; asc. over broken SE. slope.						
19.960	Point for the E 1/16 sec. cor. of secs. 3 and 34.						
	<p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 10 ins. in the ground, to solid rock, supported in a mound of stone, 4 ft. base, to top, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto;"> <tr> <td style="padding-right: 10px;">E 1/6</td> <td style="border-left: 1px solid black; padding-left: 5px;">S 34</td> </tr> <tr> <td></td> <td style="border-left: 1px solid black; padding-left: 5px;">S 3</td> </tr> <tr> <td></td> <td style="border-left: 1px solid black; padding-left: 5px;">1988</td> </tr> </table> </div> <p>from which</p> <p style="margin-left: 40px;">A cedar, 33 ins. diam., bears N. 55½° E., 181 lks. dist., mkd. E 1/16 S34 BT.</p> <p style="margin-left: 40px;">A cedar, 21 ins. diam., bears S. 38½° E., 91 lks. dist., mkd. E 1/16 S3 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Continue over SE. slope.</p>	E 1/6	S 34		S 3		1988
E 1/6	S 34						
	S 3						
	1988						
28.30	Spur, slopes S.; desc. over broken SW. slope.						
39.920	<p>The ¼ sec. cor. of secs. 3 and 34, perpetuated and recorded by G.G. Stewart, Deputy County Surveyor, in 1922, and further perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1961, determined from an original bearing tree:</p> <p style="margin-left: 40px;">An oak, 21 ins. diam., bears S. 82½° W., 355 lks. dist., with open and rotted blaze.</p> <p>and a bearing tree mkd. by Stewart</p> <p style="margin-left: 40px;">An oak, 42 ins. diam., bears S. 38° W., 223 lks. dist., with open and rotted blaze.</p> <p>and bearing trees mkd. by Byron</p> <p style="margin-left: 40px;">A fir, 18 ins. diam., bears S. 54½° W., 268 lks. dist., with healed blaze.</p>						