

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the East Boundary,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18695

CHAINS

A sawed and burnt fir stump, 36 ins. diam., bears
S. $21\frac{1}{2}^{\circ}$ E., 38 lks. dist., no visible marks.

A fir, 42 ins. diam., bears N. 26° W., 67 lks. dist.,
with a partially healed, burned blaze.

At the corner point

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins.
in the ground, directly over the iron rod, with brass cap mkd.

N 1/16
S 25|S 30
1988

from which a new bearing tree

A fir, 28 ins. diam., bears S. 20° W., 47 lks. dist.,
mkd. N 1/16 S25 BT.

No suitable tree available in sec. 30.

The corner is located at the top of ascent, slopes W.

N. $0^{\circ} 19' 00''$ W., beginning new measurement.

Descend over NW. slope.

7.60 Ravine, drains N. 20° W.; asc. over SE. slope.

20.060 The cor. of secs. 19, 24, 25, and 30, monumented with an iron
post, $1\frac{1}{4}$ ins. diam., firmly set, projecting 19 ins. above ground,
with brass cap mkd.

COUNTY SURVEYORS OFFICE
T 28 S
R S 24|S 19 R
5 S 25|S 30 4
W W
1961

from which the remains of a bearing tree mkd. by James W. Byron,
Deputy County Surveyor, in 1961

A burnt cedar snag, 22 ins. diam., bears S. 24° E.,
16 lks. dist., no marks remaining.

and the remains of a bearing tree mkd. by Popken

A burnt pine snag, 16 ins. diam., bears N. 58° W.,
93 lks. dist., with healed blaze. (Record, N. 54° W.,
105 lks.)

and new bearing trees

A cedar, 13 ins. diam., bears N. $73\frac{1}{2}^{\circ}$ E., 485 lks. dist.,
mkd. T28S R4W S19 BT.

A pine, 9 ins. diam., bears S. 81° E., 312 lks. dist.,
mkd. T28S R4W S30 BT.

A fir, 4 ins. diam., bears S. 45° W., 372 lks. dist.,
mkd. X BT.

A cedar, 18 ins. diam., bears N. $27\frac{1}{4}^{\circ}$ W., 181 lks. dist.,
mkd. T28S R5W S24 BT.