

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18703

CHAINS									
	<p>from which a new bearing tree</p> <p style="padding-left: 40px;">A fir, 18 ins. diam., bears S. <math>45\frac{1}{2}^{\circ}</math> W., 17 lks. dist., mkd. <math>\frac{1}{4}</math> S34 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base and the iron pipe alongside the stainless steel post.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. <math>0^{\circ} 58' 00''</math> E., beginning new measurement.</p> <p>Ascend over broken S. slope, through open pastureland.</p>								
0.05	Wire fence, bears W. and E. turning S.								
19.600	<p>Point for the N 1/16 sec. cor. of secs. 34 and 35.</p> <p>Set a stainless steel post, 28 ins. long, <math>2\frac{1}{2}</math> ins. diam., 23 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: 0 auto;"> <tr><td colspan="2">N 1/16</td></tr> <tr><td>S 34</td><td>S 35</td></tr> <tr><td colspan="2">1988</td></tr> </table> </div> <p>from which</p> <p style="padding-left: 40px;">An oak, 10 ins. diam., bears N. <math>21\frac{1}{2}^{\circ}</math> E., 57 lks. dist., mkd. N 1/16 S35 BT.</p> <p style="padding-left: 40px;">An oak, 9 ins. diam., bears S. <math>60\frac{3}{4}^{\circ}</math> W., 132 lks. dist., mkd. N 1/16 S34 BT.</p> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>Begin descent over broken NW. slope.</p>	N 1/16		S 34	S 35	1988			
N 1/16									
S 34	S 35								
1988									
28.30	Dirt road, 20 lks. wide, bears N. $60^{\circ}$ E. and S. $60^{\circ}$ W.								
39.200	<p>Point for the cor. of secs. 26, 27, 34 and 35, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set a stainless steel post, 28 ins. long, <math>2\frac{1}{2}</math> ins. diam., 22 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: 0 auto;"> <tr><td colspan="2">T 28 S R 5 W</td></tr> <tr><td>S 27</td><td>S 26</td></tr> <tr><td>S 34</td><td>S 35</td></tr> <tr><td colspan="2">1988</td></tr> </table> </div> <p>Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.</p> <p>From this point, a point established and recorded by John M. Markham Jr., Registered Engineer No. 2880, in 1950, perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1961, bears N. <math>36^{\circ} 40'</math> E., 0.395 chs. dist., monumented with an iron post, <math>1\frac{1}{4}</math> ins. diam., firmly set, projecting 18 ins. above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE T28S R5W S26 S27 S34 S35 1961. The Douglas County Records File 40, page 272, indicates that erroneous original record distances were used to determine the position of this monument, therefore this position is not utilized in this survey. From this local corner, the remains of the bearing trees mkd. by Markham:</p> <p style="padding-left: 40px;">A sawed oak stump, 14 ins. diam., bears N: <math>1^{\circ}</math> E., 467 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">An oak, 20 ins. diam., bears N. <math>64\frac{1}{4}^{\circ}</math> E., 317 lks. dist., with healed blaze.</p>	T 28 S R 5 W		S 27	S 26	S 34	S 35	1988	
T 28 S R 5 W									
S 27	S 26								
S 34	S 35								
1988									