

# County Surveyor's Record, Douglas County, Oregon

18706

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 28 S., R. 5 W., Willamette Meridian, Oregon

CHAINS																	
	Descend over broken NE. slope.																
52.10	Creek, 3 lks. wide, course N. 40° W.; asc. over broken SW. slope.																
58.10	Spur, slopes N. 80° W.; cross broken W. slope.																
66.40	Begin descent over broken NW. slope.																
76.30	Ravine, drains W.; cross W. slope, through scattering timber and dense undergrowth.																
78.360	Point for the cor. of secs. 22, 23, 26 and 27, at proportionate distance; there is no remaining evidence of the original corner.																
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.																
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="4">T 28 S R 5 W</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 22</td> <td style="padding: 0 5px;">S 23</td> <td colspan="2"></td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 27</td> <td style="padding: 0 5px;">S 26</td> <td colspan="2"></td> </tr> <tr> <td colspan="4" style="text-align: center;">1988</td> </tr> </table>	T 28 S R 5 W				S 22	S 23			S 27	S 26			1988			
T 28 S R 5 W																	
S 22	S 23																
S 27	S 26																
1988																	
	from which																
	A fir, 4 ins. diam., bears N. 67¼° E., 104 lks. dist., mkd. X BT.																
	A fir, 8 ins. diam., bears S. 2½° E., 59 lks. dist., mkd. T28S R5W S26 BT.																
	A fir, 4 ins. diam., bears S. 53¾° W., 49 lks. dist., mkd. X BT.																
	A fir, 13 ins. diam., bears N. 32° W., 102 lks. dist., mkd. T28S R5W S22 BT.																
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.																
	From the cor. of secs. 23, 24, 25 and 26.																
	S. 88° 50' 00" W., bet. secs. 23 and 26.																
	Descend over broken NW. slope, through open pastureland.																
16.10	Creek, 5 lks. wide, course S. 55° W.; asc. over broken SE. slope.																
21.20	Spur, slopes S. 60° W.; desc. over broken SW. slope.																
37.80	Graveled road, 15 lks. wide, bears N. 30° E. and S. 30° W.; enter scattering timber and dense undergrowth.																
39.945	Point for the ¼ sec. cor. of secs. 23 and 26, at proportionate distance; there is no remaining evidence of the original corner.																
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.																
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="4">T 28 S R 5 W</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">¼ S 23</td> <td style="padding: 0 5px;">S 26</td> <td colspan="2"></td> </tr> <tr> <td colspan="4" style="text-align: center;">1988</td> </tr> </table>	T 28 S R 5 W				¼ S 23	S 26			1988							
T 28 S R 5 W																	
¼ S 23	S 26																
1988																	
	from which																
	An oak, 12 ins. diam., bears S. 24½° W., 96 lks. dist., mkd. ¼ S26 BT.																
	A cedar, 10 ins. diam., bears N. 20¾° W., 49 lks. dist., mkd. ¼ S23 BT.																
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.																