

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 25,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18713

CHAINS	
	C S 1/16 S 25 C 1988
	from which A fir, 12 ins. diam., bears S. 37 $\frac{1}{4}$ ° E., 59 $\frac{1}{2}$ lks. dist., mkd. X BT. A fir, 18 ins. diam., bears N. 47 $\frac{1}{2}$ ° W., 69 $\frac{1}{2}$ lks. dist., mkd. CS 1/16 S25 BT. Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post. Ascend over SW. slope.
20.55	Rocky spur, slopes S. 80° W.; desc. over NW. slope.
31.00	Creek, 1 lk. wide, course S. 80° W.; asc. over steep, broken slope.
36.50	Spur, slopes S. 50° W.; desc. along W. slope.
39.600	True point for the center $\frac{1}{4}$ sec. cor. of sec. 25, at intersection with the E. and W. center line, is located on a rock face, where it is impracticable to establish a permanent monument.
40.000	Point selected for the witness cor. to the center $\frac{1}{4}$ sec. cor. of sec. 25. Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 22 ins. in the ground, with brass cap mkd.
	W C T 28 S R 5 W C $\frac{1}{4}$ S 25 ↓ 1988
	from which A fir, 10 ins. diam., bears N. 50 $\frac{1}{2}$ ° E., 32 lks. dist., mkd. X BT. A fir, 32 ins. diam., bears S. 48 $\frac{1}{2}$ ° W., 170 lks. dist., mkd X BT. Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post. The corner is located on a steep NW. slope. Descend along NW. slope.
56.15	Ravine, drains SW.; asc. along broken SW. slope.
59.00	Woven wire fence, bears E. and S. 70° W.
59.510	Point for the center N 1/16 sec. cor. of sec. 25. Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 12 ins. in the ground, to solid rock, in a mound of stone, 3 ft. base, to top, with brass cap mkd.
	C N 1/16 S 25 C 1988