

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 25,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18715

CHAINS	
	S. 88° 34' 30" W., on the E. and W. center line of the NE¼ of sec. 25.
	Descend over NW. slope, through open pasture.
3.75	Creek, 5 lks. wide, course S. 10° W.; asc. over broken SE. slope.
8.75	Spur, slopes S.; desc. over SW. slope.
14.35	Creek, 8 lks. wide, course S. 5° E.; asc. over SE. slope.
24.50	Woven wire fence, bears N. 80° E. and S. 80° W.
33.75	Ridge, bears N. and S.; desc. over SW. slope.
40.160	The center N 1/16 sec. cor. of sec. 25.
<hr/>	
	From the W 1/16 sec.cor. of secs. 25 and 36.
	N. 0° 17' 00" W., on the N. and S. center line of the SW¼ of sec. 25.
	Ascend over broken SW. slope, through heavy timber and light undergrowth.
16.80	Ridge, bears S. 60° E. and N. 20° W.; desc. over broken NE. slope.
19.800	The SW 1/16 sec. cor. of sec. 25, established and recorded by Burton H. Holt, Registered Land Surveyor No. 418, in 1981, and is accepted as the corner, monumented with an iron pipe, 1 in dia., firmly set, projecting 4 ins. above ground, from which bearing trees mkd. by Holt:
	A burned cedar, 10 ins. diam., bears S. 27¼° E., 101 lks. dist., with scribe marks SW 1/16 S25 BT visible on partially healed blaze.
	A fir, 22 ins. diam., bears N. 6½° W., 26 lks. dist., with illegible scribe marks visible on partially healed, burned blaze.
	At the corner point
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over the iron pipe, with brass cap mkd.
	SW 1/16 S 25 1988
	from which a new bearing tree
	A fir, 20 ins. diam., bears S. 78½° E., 125 lks. dist., mkd. SW 1/16 S25 BT.
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
	<hr/>
	N. 0° 13' 00" W., beginning new measurement.
	Descend over broken NE. slope.
16.60	Creek, 1 lk. wide, course SE.; asc. over SE. slope.
19.760	The center W 1/16 sec. cor. of sec. 25
<hr/>	