

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 26,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18719

CHAINS

- 0.05 Spur, slopes S.; desc. over SW. slope.
- 3.55 Ravine, drains S. 10° E.; asc. over SE. slope.
- 19.50 Leave timber; enter open pasture, edge bears N. and S.
- 20.065 The SW 1/16 sec. cor. of sec. 26.
Ascend over NE. slope, through open pasture.
- 22.25 Dirt road, 15 lks. wide, bears N. 25° E. and S. 35° W.
- 24.00 Ridge, bears N. 10° E. and S. 25° W.; desc. over broken SW. slope.
- 40.130 The S 1/16 sec. cor. of secs. 26 and 27.

Subdivision of Section 27,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

- From the ¼ sec. cor. of secs. 27 and 34.
- N. 0° 04' 00" W., on the N. and S. center line of section 27.
- Descend over NW. slope, through heavy timber and dense undergrowth.
- 19.835 Point for the center S 1/16 sec. cor. of sec. 27.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

C
S 1/16 | S 27
C
1988

from which

A cedar, 12 ins. diam., bears S. 20° E., 15½ lks. dist., mkd. CS 1/16 S27 BT.

A fir, 7 ins. diam., bears S. 64° W., 38 lks. dist., mkd. CS 1/16 S27 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

Descend over NE. slope.

- 21.70 Roberts Creek, 6 lks. wide, course N. 85° W.; asc. over SW. slope.
- 24.15 Spur, slopes NW.; desc. over broken NW. slope.
- 28.20 Creek, 4 lks. wide, course N. 60° W.; continue descent over broken NW. slope.
- 29.25 Creek, 3 lks. wide, course S. 80° W.; continue descent over broken NW. slope.
- 34.60 Ravine, drains S. 70° W.; asc. over SE. slope.
- 37.25 Woven wire fence, bears N. 60° E. and S. 60° W.
- 39.670 Point for the center ¼ sec. cor. of sec. 27, at intersection with the E. and W. center line.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 6 ins. in the ground to bedrock, supported in a mound of stone, 3 ft. base, to top, with brass cap mkd.