

County Surveyor's Record, Douglas County, Oregon

18724

Subdivision of Section 34,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

CHAINS	
43.65	Dirt road, 15 lks. wide, bears N. 10° E. and S. 10° W.
79.560	The ¼ sec. cor. of secs. 33 and 34.
<hr/>	
From the E 1/16 sec. cor. of secs. 3 and 34, on the S. bdy. of the Tp.	
N. 0° 27' 00" W., on the N. and S. center line of the SE¼ of sec. 34.	
Ascend over SE. slope, through open pasture and scattered timber.	
13.75	Ridge, bears N. 60° E. and S. 70° W.; desc. over broken NW. slope.
19.40	Woven wire fence, bears N. 70° E. and S. 70° W.
20.040	Point for the SE 1/16 sec. cor. of sec. 34, at intersection with the E. and W. center line of the SE¼.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.	
SE 1/16 S 34 1988	
from which	
A cedar, 11 ins. diam., bears N. 31° E., 22½ lks. dist., mkd. SE 1/16 S34 BT.	
A cedar, 8 ins. diam., bears S. 22½° E., 39 lks. dist., mkd. X BT.	
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.	
Descend over broken NW. slope.	
24.00	Dirt road, 15 lks. wide, bears N. 45° E. and S. 55° W.
40.080	The center E 1/16 sec. cor. of sec. 34.
<hr/>	
From the S 1/16 sec. cor. of secs. 34 and 35.	
S. 89° 31' 30" W., on the E. and W. center line of the SE¼ of sec. 34.	
Ascend over broken E. slope, through scattered timber and light undergrowth.	
12.35	Dirt road, 15 lks. wide, bears N. 10° W. and S. 10° E.
17.15	Spur, slopes N.; desc. over broken NW. slope.
17.45	Woven wire fence, bears N. 80° E. and S. 80° W.
19.830	The SE 1/16 sec. cor. of sec. 34.
Descend over broken NW. slope, through open pasture and scattered timber.	
30.50	Dirt road, 20 lks. wide, bears N. 60° E. and S. 60° W.
39.660	The center S 1/16 sec. cor. of sec. 34.
<hr/>	