

County Surveyor's Record, Douglas County, Oregon

18726

Subdivision of Section 35,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

CHAINS										
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.									
	Ascend over SW. slope.									
65.05	Ridge, bears S. 70° E. and S. 70° W.; desc. over N. slope.									
70.25	Creek, 2 lks. wide, course N. 50° E.; asc. over SE. slope.									
75.40	Spur, slopes E.; desc. over NE. slope.									
79.270	The $\frac{1}{4}$ sec. cor. of secs. 26 and 35.									
	<hr/> From the $\frac{1}{4}$ sec. cor. of secs. 35 and 36.									
	S. 89° 57' 30" W., on the E. and W. center line of sec. 35.									
	Ascend over SE. changing to NE. slope, through heavy timber and dense undergrowth.									
11.25	Ridge, bears N. 20° W. and S. 15° E.; desc. over SW. slope.									
22.35	Ravine, drains S. 25° W.; asc. over SE. slope									
29.00	Spur, slopes S. 20° W.; desc. over W. slope.									
35.00	Creek, 1 lk. wide, course S.; asc. over broken SE. slope.									
40.140	The center $\frac{1}{4}$ sec. cor. of sec. 35.									
	Ascend over broken SE. slope.									
59.80	Creek, 2 lks. wide, course S. 50° E.; continue ascent over broken SE. slope.									
60.465	Point for the center W 1/16 sec. cor. of sec. 35.									
	Set a stainless steel post, 28 ins. long, 2½ ins. diam., 20 ins. in the ground, with brass cap mkd.									
	<table style="margin: auto; border: none;"> <tr> <td style="padding: 0 10px;">C</td> <td style="text-align: center; border-bottom: 1px solid black;">W 1/16</td> <td style="padding: 0 10px;">C</td> </tr> <tr> <td></td> <td style="text-align: center;">S 35</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">1988</td> <td></td> </tr> </table>	C	W 1/16	C		S 35			1988	
C	W 1/16	C								
	S 35									
	1988									
	from which									
	A fir, 21 ins. diam., bears S. 64° W., 74 lks. dist., mkd. CW 1/16 S35 BT.									
	A cedar, 18 ins. diam., bears N. 31½° W., 46 lks. dist., mkd. CW 1/16 S35 BT.									
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.									
	Ascend over broken SE. slope.									
66.50	Spur, slopes S. 5° W.; desc. over SW. slope.									
80.790	The $\frac{1}{4}$ sec. cor. of secs. 34 and 35.									
	<hr/> From the center W 1/16 sec. cor. of sec. 35.									
	N. 0° 37' 00" E., on the N. and S. center line of the NW¼ of sec. 35.									
	Descend along E. slope, through heavy timber and light undergrowth.									
0.60	Creek, 1 lk. wide, course S. 60° E.; asc. over broken SE. slope.									