

# County Surveyor's Record, Douglas County, Oregon

18756

Corrective Dependent Resurvey of a Portion of the East Boundary,  
T. 19 S., R. 10 W., Willamette Meridian, Oregon

CHAINS																
29.90	Bottom of descent, slopes E.; asc. E. slope.															
32.10	Spur, slopes E.; desc. E. slope.															
34.50	Bottom of descent, slopes S. 80° E.; asc. E. slope.															
36.40	Spur, slopes E.; desc. NE. slope.															
38.25	Bottom of descent, slopes E.; asc. SE. slope.															
39.000	<p>Point for the cor. of secs. 1 and 12 only, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>From this point, the cor. of secs. 1 and 12 only, erroneously reestablished by Tillman, Holm, and Brooks in 1957-58, bears N. 16° 20' W., 0.242 chs. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, mkd. and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1989 1958, reset the monument flush with the ground surface, and at the true corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd:</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="2" style="padding: 0 10px;">T19S</td> <td></td> </tr> <tr> <td style="padding: 0 5px;">R10W</td> <td style="padding: 0 5px;">R9W</td> <td></td> </tr> <tr> <td style="padding: 0 5px;">S 1</td> <td style="border-left: 1px solid black; padding: 0 5px;"></td> <td style="padding: 0 5px;">S 7</td> </tr> <tr> <td style="padding: 0 5px;">S 12</td> <td style="border-left: 1px solid black; padding: 0 5px;"></td> <td></td> </tr> <tr> <td colspan="2" style="padding: 0 10px;">1989</td> <td></td> </tr> </table> </div> <p>from which the bearing trees mkd. by Tillman, Holm and Brooks</p> <p style="margin-left: 40px;">A fir, 33 ins. diam., bears N. 53½° W., 148 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 30 ins. diam., bears N. 56° W., 52 lks. dist., with healed blaze.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p> <hr style="width: 80%; margin: 10px auto;"/> <p>N. 0° 44' 30" E., on the E. bdy. of sec. 1.</p> <p>Ascend SE. slope, through timber.</p>	T19S			R10W	R9W		S 1		S 7	S 12			1989		
T19S																
R10W	R9W															
S 1		S 7														
S 12																
1989																
1.35	Spur, slopes S. 40° E.; desc. NE. slope.															
4.60	Creek, 1 lk. wide, course S. 70° E.; asc. SE. slope.															
9.50	Gravel road, 15 lks. wide, bears N. 60° E. and S. 60° W.															
9.870	True point for the closing cor. of secs. 6 and 7, T. 19 S., R. 9 W., hereinafter described.															
	Ascend S. slope, logged area to E. and timber to W., posting true line.															
10.90	Spur, slopes S. 40° E.; desc. NE. slope.															
12.00	Enter logged area, edge bears S. and W.															
14.20	Bottom of descent, slopes E.; asc. SE. slope.															
14.90	Spur, slopes N. 50° E.; desc. NW. changing to NE. slope.															
26.40	Dry creek bed, 3 lks. wide, course N. 40° E.; asc. SE. slope.															
28.820	Point for the S 1/16 sec. cor. of sec. 6 only, T. 19 S., R. 9 W.															