

County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey of a Portion of the East Boundary,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18757

CHAINS

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd:

| S 1/16
| S 6
1989

from which

A stainless steel post, 28 ins. long, 2½ ins. diam., set 28 ins. in the ground, for a reference monument, bears N. 89° 12' E., 69.5 lks. dist., with brass cap mkd. RM S1/16 S6 45.9 FT. TO COR 1989 and an arrow pointing to the corner.

and the bearing trees mkd. by Donald L. Peel, Registered Land Surveyor No. 752, in 1979, and recorded in Lane County Survey No 22,751.

A hemlock, 25 ins. diam., bears N. 54½° E., 22 lks. dist. with fragmentary scribe marks visible in partially healed blaze.

A fir, 60 ins. diam., bears N. 0½° W., 55 lks. dist., with healed double blaze.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Corner is located on a spur, slopes E.

From this point, a point established as the S 1/16 sec. cor. of sec. 6 only, T. 19 S., R. 9 W., by Alan D. Reid, U.S. Forest Service Forester, in 1958, record held at Mapleton Ranger Station, bears N. 12¼° E., 0.076 chs. dist., monumented with an iron pipe, 1½ ins. diam., firmly set, 2 ins. below ground surface. This point was not established by a registered land surveyor/engineer, was established using improper control and is not utilized in this survey, from which the remains of bearing trees mkd. by Reid:

A root hole, bears S. 80½° E., 34 lks. dist., lying alongside is a hemlock, 16 ins. diam., with rotted blaze.

A root hole, bears N. 18½° W., 17 lks. dist., lying alongside is a fir, 60 ins. diam., with scribe marks 1/16 visible in partially healed blaze and a 3/8 in. iron spike driven in face.

From this same point, a point established as the S 1/16 sec. cor. of sec. 6 only, T. 19 S., R. 9 W., by Donald L. Peel, Registered Land Surveyor No. 752, in 1979, and recorded in Lane County Survey No. 22,751, bears S. 78¾° W., 0.015 chs. dist., monumented with an aluminum post, 2½ ins. diam., firmly set, projecting 2 ins. above ground, with aluminum cap mkd. T19S R9W S1/16 S6 PLS752 1979. This point was established using improper control and is not utilized in this survey.

Descend NE. slope.

30.930

From this point, a point established as the ¼ sec. cor. of sec. 1 only, by Chandler in 1895, and subsequently destroyed by Chandler in 1899, bears East, 0.065 chs. dist., determined at Gerdine's record bearing and distance from the remaining original bearing tree:

A fir stump, 48 ins. diam., bears S. 45° E., 15 lks. dist., with healed blaze; opened the blaze and found axe marks on an obliterated face. (Chandler record, S. 41° E., 80 lks.)

At the corner point