

# County Surveyor's Record, Douglas County, Oregon

18764

Dependent Resurvey of a Portion of the Subdivisional Lines,  
T. 19 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

of two very high waterfalls. From the falls south along the river there is a trail under construction. The private land is logged timberland.

An abandoned quarry is located in section 7. No other evidence of mineral deposits was noted in the area covered by this resurvey.

The mean magnetic declination is  $18\frac{1}{2}^{\circ}$  East, with a range of  $\frac{1}{2}^{\circ}$  noted.