

County Surveyor's Record, Douglas County, Oregon

9

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18773

CHAINS

T19S	R10W
S 26	S 25
S 35	S 36
1971	
4185	

from which the remains of bearing trees mkd. by Prochnau

A fir, 30 ins. diam., bears N. 7° E., 46½ lks. dist.,
with healed blaze.

A fir stump, 33 ins. diam., bears S. 65½° E., 33 lks.
dist., with healed blaze.

A fir, 23 ins. diam., bears S. 49½° W., 83 lks. dist.,
with healed blaze.

A fir, 43 ins. diam., bears N. 11¼° W., 50 lks. dist.,
with healed blaze.

and a new bearing tree

A hemlock, 9 ins. diam., bears S. 71½° E., 51 lks. dist.,
mkd. T19S R10W S36 BT.

Corner is located on a NW. slope, at NW. corner of logged area.

From this point (cor. of secs. 25, 26, 35 and 36), the United States
Forest Service GPS Station No. 191036, bears S. 19° 44' 00" E.,
59.010 chs. dist., monumented with an iron rod, 5/8 in. diam.,
firmly set in concrete, flush with ground surface, with aluminum cap
mkd. GPS 191036 + 1988.

These control lines were fully retraced and careful search was made
for evidence of the intervening corners, none of which were
recovered.

N. 3° 45' 30" E., bet. secs. 23 and 24.

Ascend S. slope, through timber.

0.30 Spur, slopes S. 80° W.; desc. broken N. slope.

22.40 U.S. Forest Service Road No. 48-922, gravel, 25 lks. wide, bears N.
80° W. and S. 80° E.; desc. broken NW. slope.

38.00 Creek, 3 lks. wide, course E.; asc. broken S. slope.

46.070 Point for the ¼ sec. cor. of secs. 23 and 24, at proportionate
distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 23 ins. in
the ground, with brass cap mkd:

T19S	R10W
¼	
S 23	S 24
1989	

from which

A fir, 46 ins. diam., bears N. 74½° E., 21 lks. dist.,
mkd. ¼ S24 BT.

A cedar, 14 ins. diam., bears N. 38¼° W., 36½ lks. dist.,
mkd. ¼ S23 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel
post.