

County Surveyor's Record, Douglas County, Oregon

18778

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

CHAINS									
	<p>A fir, 32 ins. diam., bears S. 75° E., 41 lks. dist., mkd. $\frac{1}{4}$ S13 BT.</p> <p>A fir, 28 ins. diam., bears S. 30° W., 25 lks. dist., mkd. $\frac{1}{4}$ S14 BT.</p> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p> <p>Ascend SW. slope, through timber.</p>								
47.60	Spur, slopes N. 40° W.; desc. broken NE. slope.								
83.00	U.S. Forest Service Road No. 4890-915, gravel, 25 lks. wide, bears N. 70° E. and S. 50° W., in a curve; asc. broken S. slope.								
85.40	U.S. Forest Service Road No. 4890-916, gravel, 25 lks. wide, bears N. 50° W. and S. 60° E., in a curve, desc. NE. changing to E. slope.								
92.110	<p>The cor. of secs. 11, 12, 13 and 14, monumented with the remains of the original corner tree, an alder snag, 20 ins. diam., 1 ft. high, no marks, from which the remains of the original bearing trees:</p> <p style="margin-left: 40px;">A fir stump, 46 ins. diam., 6 ft. high, bears S. 37$\frac{1}{2}$° E., 83 lks. dist., with healed blaze. (Record, S. 38° E., 87 lks.)</p> <p style="margin-left: 40px;">A fir stump, 30 ins. diam., 6 ft. high, bears S. 6° W., 56 lks. dist., with healed blaze. Remarkd by John M. Powell et al., of the Douglas County Surveyor's Office, in 1971, and recorded as Douglas County Corner Renewal No. 13 and Lane County Reestablishment No. 5331, with scribe marks T19S R10W S14 CS BT visible on unhealed blaze. (Record, S. 8° W.)</p> <p>and the remains of a bearing tree mkd. by Alan D. Reid, Forester, U.S. Forest Service, in 1958, and recorded as Lane County Reestablishment No. 2183 and Douglas County Corner Renewal No. 12:</p> <p style="margin-left: 40px;">A fir stump, 26 ins. diam., 10 ft. high, bears N. 34$\frac{1}{2}$° E., 95 lks. dist., with healed blaze.</p> <p>and accessories established by John M. Powell et al., of the Douglas County Surveyor's Office, in 1971, and recorded as Douglas County Survey Corner Renewal No. 13 and Lane County Reestablishment No. 5331:</p> <p style="margin-left: 40px;">An iron rod, 5/8 in. diam., firmly set, projecting 6 ins. above ground, bears N. 29° 56' E., 57.8 lks. dist.</p> <p style="margin-left: 40px;">An iron post, 1$\frac{1}{2}$ ins. diam., firmly set, projecting 8 ins. above ground, bears N. 4° 38' W., 2.0 lks. dist., with brass cap mkd. T19S S11 S12 S13 S14 R10W 1971, and with an iron pipe, 1$\frac{1}{2}$ ins. diam., buried alongside.</p> <p>The iron rod set to the NW. was found lying loose on the ground.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2$\frac{1}{2}$ ins. diam., 24 ins. in the ground, and in the center of the corner tree, with brass cap mkd:</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 10px;">T 19 S</td> <td style="padding: 0 10px;">R10W</td> </tr> <tr> <td style="padding: 0 10px;">S 11</td> <td style="padding: 0 10px;">S 12</td> </tr> <tr> <td style="padding: 0 10px;">S 14</td> <td style="padding: 0 10px;">S 13</td> </tr> <tr> <td colspan="2" style="padding: 0 10px;">1988</td> </tr> </table> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 10 ins. diam., bears S. 5$\frac{1}{4}$° E., 27$\frac{1}{2}$ lks. dist., mkd. T19S R10W S13 BT.</p>	T 19 S	R10W	S 11	S 12	S 14	S 13	1988	
T 19 S	R10W								
S 11	S 12								
S 14	S 13								
1988									