

County Surveyor's Record, Douglas County, Oregon

18786

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

CHAINS									
33.50	Creek, 2 lks wide, course S. 50° W.; asc. SE. slope, over small spur.								
36.00	Creek, 2 lks. wide, course S. 20° W.; asc. SE. slope.								
37.70	Top of ascent; over nearly level land.								
38.740	<p>The cor. of secs. 27, 28, 33 and 34, monumented with the original corner tree, a rotted fir snag, 16 ins. diam., 2 ft. high, with fragmentary scribe marks visible on loose piece lying at base, from which the remains of the original bearing trees:</p> <p style="margin-left: 40px;">A fir snag, 12 ins. diam., 5 ft. high, bears N. 27° E., 18 lks. dist., with scribe marks T19S R10W S27 visible on opened blaze. (Record, N. 30° E.)</p> <p style="margin-left: 40px;">A fir snag, 16 ins. diam., 20 ft. high, bears S. 60° E., 25 lks. dist., with healed blaze. (Record, 19 lks.)</p> <p style="margin-left: 40px;">A fir, 40 ins. diam., bears S. 51° W., 19 lks. dist., with two healed blazes. (Record, 25 lks.)</p> <p style="margin-left: 40px;">A fir snag, 17 ins. diam., 10 ft. high, bears N. 39° W., 16 lks. dist., no marks visible on opened blaze.</p> <p>and the accessories mkd. by Vernon "Ray" Tracy et al., of the Douglas County Surveyor's Office, in 1968, and recorded in Douglas County Corner Renewal No. 10</p> <p style="margin-left: 40px;">A fir, 20 ins. diam., bears N. 89° E., 42 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 43 ins. diam., bears S. 65° E., 71 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">A fir, 25 ins. diam., bears N. 71° W., 20 lks. dist., with healed blaze.</p> <p style="margin-left: 40px;">An iron post, 1 in. diam., firmly set, projecting 6 ins. above ground, bears N. 58° 29' W., 2.0 lks. dist., with brass cap mkd. T19S WIT COR S27 S28 S33 S34 S58 29E 1.3 FT R10W 1968.</p> <p>At the corner point</p> <p>Set a stainless steel post, in the center of the corner tree, 28 ins. long, 2½ ins. diam., 23 ins. in the ground, with brass cap mkd:</p> <table style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <tr> <td style="padding: 0 10px;">T19S</td> <td style="border-left: 1px solid black; padding: 0 10px;">R10W</td> </tr> <tr> <td style="padding: 0 10px;">S 28</td> <td style="border-left: 1px solid black; padding: 0 10px;">S 27</td> </tr> <tr> <td style="padding: 0 10px;">S 33</td> <td style="border-left: 1px solid black; padding: 0 10px;">S 34</td> </tr> <tr> <td colspan="2" style="text-align: center; padding: 0 10px;">1988</td> </tr> </table> <p>Deposit white "DEEP-1" magnetic marker at base of stainless steel post.</p> <hr style="width: 80%; margin: 10px auto;"/> <p>N. 0° 10' 30" W., bet. secs. 27 and 28.</p> <p>Ascend gradual S. slope, through timber.</p>	T19S	R10W	S 28	S 27	S 33	S 34	1988	
T19S	R10W								
S 28	S 27								
S 33	S 34								
1988									
12.00	Begin steeper ascent up S. sloping spur.								
24.00	Slope changes to SW.								
31.10	Spur, slopes N. 80° W.; desc. broken N. slope.								
42.70	U.S. Forest Service Road No. 4820, gravel, 30 lks. wide, bears N. and S.; desc. NE. slope, enter logged area.								