

County Surveyor's Record, Douglas County, Oregon

18792

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

CHAINS

A fir stump, 20 ins. diam., 1 ft. high, bears N. $47\frac{1}{4}^{\circ}$ W.,
26 lks. dist., no marks. (Record, N. 44° W., 28 lks.)

and the bearing trees mkd. by Mitchell

A fir, 30 ins. diam., bears S. 17° W., 22 lks. dist.,
with healed blaze.

A fir, 28 ins. diam., bears S. 73° W., $41\frac{1}{2}$ lks. dist.,
with healed blaze.

A fir, 30 ins. diam., bears N. $63\frac{3}{4}^{\circ}$ W., 99 lks. dist.,
with healed blaze.

A rusted iron pipe filled with concrete is buried alongside the iron post.

Corner is located on level ground, in timber.

From this point (cor. of secs. 19, 24, 25 and 30), the United States Forest Service GPS Station No. 191019, bears N. $78^{\circ} 10' 10''$ E., 26.626 chs. dist., monumented with an iron rod, $\frac{5}{8}$ in. diam., firmly set in concrete, flush with ground surface, with aluminum cap mkd. GPS 191019 + 1988.

Also, from the cor. of secs. 20, 21, 28 and 29, the cor. of secs. 8, 9, 16 and 17, bears N. $1^{\circ} 40' 30''$ E., 180.990 chs. dist., reestablished by single proportionate measurement E. and W. by Donald L. Peel, Registered Land Surveyor No. 752, in 1980, and recorded in Lane County Survey No. 24,398; there is no remaining evidence of the original corner. This position has been recognized as the corner by adjacent landowners, and is accepted as a careful and faithful reestablishment of the position of the original corner; monumented with an aluminum post, $2\frac{1}{2}$ ins. diam. firmly set, projecting 6 ins. above ground, with aluminum cap mkd.

T19S	R10W
S 8	S 9
S 17	S 16
PLS 752	
1980	

from which the new bearing trees mkd. by Peel

A fir, 12 ins. diam., bears N. 20° E., 17 lks. dist.,
with healed double blaze.

A fir, 13 ins. diam., bears S. $54\frac{1}{2}^{\circ}$ E., 32 lks. dist.
with healed double blaze.

A fir, 13 ins. diam., bears S. 59° W., 25 lks. dist.,
with healed double blaze.

A fir, 14 ins. diam., bears N. 60° W., 17 lks. dist.,
with healed double blaze.

Corner is located on a S. 10° W. slope, in logged area.

From this point (cor. of secs. 8, 9, 16 and 17), the cor. of secs. 9, 10, 15 and 16, bears N. $88^{\circ} 54' 00''$ E., 78.500 chs. dist., hereinbefore described.

From this same point (cor. of secs. 8, 9, 16 and 17), the cor. of secs. 7, 12, 13 and 18 on the W. bdy. of the Tp., bears S. $88^{\circ} 53' 00''$ W., 162.765 chs. dist., perpetuated by Jim S. Peterson, Registered Land Surveyor No. 1084, in 1985, and recorded in Lane County Survey No. 27,350; monumented with an aluminum post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 1 ins. above ground, with aluminum cap mkd.