

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18793

CHAINS

T19S
R11W R10W
S 12 | S 7
S 13 | S 18
LS 1084
1985

from which the remains of the original bearing trees

A fir stump, 28 ins. diam., 8 ft. high, bears N. 43½° E.,
26 lks. dist., with healed blaze. (Record, N. 46° E.)

A hemlock stump, 19 ins. diam., 10 ft. high, bears
S. 15° W., 20½ lks. dist., with healed blaze.
(Record, S. 13° W., 22 lks.)

and the remains of a bearing tree mkd. by Collier and Strickler

A hemlock stump, 36 ins. diam., 8 ft. high, bears
S. 47° E., 47 lks. dist., with healed blaze.

and new bearing trees

A fir, 5 ins. diam., bears N. 24½° E., 33 lks. dist.,
mkd. T19S R10W S7 BT.

A fir, 6 ins. diam., bears S. 65° E., 5½ lks. dist.,
mkd. T19S R10S S18 BT.

A fir, 4 ins. diam., bears S. 61½° W., 12½ lks. dist.,
mkd. XBT.

A fir, 6 ins. diam., bears N. 4° W., 19½ lks. dist.,
mkd. T19S R11W S12 BT.

A rusted iron pipe filled with concrete is buried alongside the aluminum cap.

Corner is located on level ground, in logged area.

These control lines were fully retraced, and careful search was made for evidence of intervening corners, none of which were recovered.

Also, from the cor. of secs. 8, 9, 16 and 17, the United States Forest Service GPS Station No. 191016B, bears S. 14° 57' 20" W., 14.521 chs. dist., monumented with an iron rod, 5/8 ins. diam., firmly set in concrete, with aluminum cap mkd. GPS 191016B + 1988.

And also, from the cor. of secs. 8, 9, 16 and 17, the United States Forest Service GPS Station No. 191017, bears S. 63° 50' 10" W., 79.003 chs. dist., monumented with an aluminum post, 2½ ins. diam., firmly set, 1 in. below ground surface, with aluminum cap mkd. GPS 191017 + 1988.

From the cor. of secs. 21, 22, 27 and 28.

S. 89° 31' 30" W., bet. secs. 21 and 28.

Ascend broken SE. slope, through timber.

15.20 U.S. Forest Service Road No. 4820, gravel, 25 lks. wide, bears N. 50° W. and S. 50° E., on ridge bears same; desc. broken SW. slope through logged area.

25.90 Same road, bears N. and S.; asc. broken E. slope.

37.70 Top of road cutbank, bears NE. and SW.; desc. over same.

38.140 Point for the ¼ sec. cor. of secs. 21 and 28, at proportionate distance; there is no remaining evidence of the original corner.