

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 13,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

18797

CHAINS

A fir, 8 ins. diam., bears N. $0\frac{1}{2}^{\circ}$ E., $24\frac{1}{2}$ lks. dist.,
mkd. SE $\frac{1}{16}$ S13 BT.

A fir, 7 ins. diam., bears N. 65° W., $48\frac{1}{2}$ lks. dist.,
mkd. X BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Ascend SW. slope, posting true line.

24.90 Spur, slopes S. 30° E.; asc. E. slope.

25.50 Top of ascent, slopes E.; desc. NE. slope.

30.60 Bottom of descent, slopes E.; asc. SE. slope.

44.30 Top of ascent, slopes E.; over rolling E. slope.

46.455 The center E $\frac{1}{16}$ sec. cor. of sec. 13.

From the S $\frac{1}{16}$ sec. cor. of sec. 13 only, on the E. bdy. of the Tp.
S. $89^{\circ} 44' 30''$ W., on the E. and W. center line of the SE $\frac{1}{4}$ of sec.
13.

Ascend E. slope up a spur, through logged area.

10.70 Leave spur, bears N. 70° W.; asc. broken SE. slope.

17.10 Overgrown rock road, 20 lks. wide, bears N. 20° E. and S. 20° W.;
asc. broken E. slope.

19.370 The SE $\frac{1}{16}$ sec. cor. of sec. 13.

Over rolling S. slope, posting true line.

20.30 Corner of timber, edge bears N. and W.; along and near S. edge of
timber.

22.10 North cutbank of overgrown rock road, bears S. 80° E. and
S. 80° W.

24.70 Ravine, drains S. 40° E.; asc. E. slope.

31.50 Spur, slopes S. 20° E.; desc. rolling S. slope.

38.710 The center S $\frac{1}{16}$ sec. cor. of sec. 13.

Subdivision of Section 24,
T. 19 S., R. 10 W., Willamette Meridian, Oregon

From the $\frac{1}{4}$ se. cor. of secs. 24 and 25.

N. $4^{\circ} 04' 00''$ E., on the N. and S. center line of sec. 24.

Descend broken NE. slope, through timber.

46.370 Point for the center $\frac{1}{4}$ sec. cor. of sec. 24, at intersection with
the E. and W. center line.

Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in
the ground, with brass cap mkd:

T19S R10W
C $\frac{1}{4}$ S 24
1989