

County Surveyor's Record, Douglas County, Oregon

18810

Subdivision of Section 18,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

CHAINS

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 16 ins. in the ground, to solid rock, supported in a mound of stone, 3 ft. base, to top, with brass cap mkd:

NE 1/16
S 18
1989

from which

A fir, 11 ins. diam., bears S. 52° E., 25 lks. dist.,
mkd. NE 1/16 S18 BT.

A fir, 9 ins. diam., bears N. 20° W., 32 lks. dist.,
mkd. NE 1/16 S18 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Continue over gentle SW. slope.

21.90 Top of ascent, slopes W.; desc. over broken NW slope.

23.40 South shore of stock pond, bears N. 70° E. and N. 60° W.

26.20 North shore of stock pond, bears S. 80° E. and S. 70° W.

30.10 Dirt road, 15 lks. wide, bears S. 65° E. and W.

39.385 The E 1/16 sec. cor. of secs. 7 and 18, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

E 1/16 $\frac{S\ 7}{S\ 18}$
1974

from which the remains of bearing trees mkd. by popken

A root hole, bears N. 27° E., 116 lks. dist., with a
down fir alongside, 12 ins. diam., with scribe marks
E 1/16 S7 BT on a partially healed blaze.

A root hole, bears S. 63° E., 74 lks. dist., with a
down cedar alongside, 14 ins. diam., with healed blaze.

and a bearing tree mkd. by Rogers and Bishop

A cedar, 17 ins. diam., bears N. 11½° W., 158 lks. dist.,
with scribe marks E 1/16 S7 BT on a partially healed blaze.

and a new bearing tree

A cedar, 16 ins. diam., bears S. 45° E., 78½ lks. dist.,
mkd. E 1/16 S18 BT.

From the N 1/16 sec. cor. of secs. 17 and 18, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, in a collar of stone, with brass cap mkd.

N 1/16
S 18 | S 17
1974

from which the bearing trees mkd. by Popken

A hemlock, 12 ins. diam., bears S. 44° E., 11 lks.
dist., with healed blaze.