

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 18,
T. 28 S., R. 4 W., Willamette Meridian, Oregon

18811

| CHAINS | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| | <p>A fir, 23 ins. diam., bears N. 39° W., 50 lks. dist., with healed blaze.</p> |
| | <p>N. 88° 46' 30" W., on the E. and W. center line of the NE¼ of sec. 18.</p> |
| | <p>Descend over broken NW slope, through scattering timber and dense undergrowth.</p> |
| 19.915 | <p>The NE 1/16 sec. cor. of sec. 18.</p> |
| | <p>Continue over broken NW slope.</p> |
| 21.90 | <p>Swampy ravine, drains N.; asc. over NE. slope.</p> |
| 26.00 | <p>Spur, slopes N.; desc. over broken NW. slope.</p> |
| 39.770 | <p>The center N 1/16 sec. cor. of sec. 18.</p> |
| <p>GENERAL DESCRIPTION</p> | |
| <p>The lands included in the foregoing survey are located in mountainous country in Douglas County about five miles south of Dixonville, Oregon. The elevations range from 1500 feet to 3000 feet above sea level.</p> | |
| <p>The drainage is northwesterly by Milton Creek. The soil is rocky clay. The timber consists of fir, hemlock, cedar, yew, oak, and madrone with undergrowth of manzanita, poison oak, huckleberry, blackberry, Oregon grape, salal, and fern.</p> | |
| <p>Access is via logging roads branching from county roads from Myrtle Creek to the south and from Dixonville to the North.</p> | |
| <p>There are abandoned copper mines in the SE¼ of section 18.</p> | |
| <p>The principle industry is timber.</p> | |
| <p>The average of numerous readings in the area gives a value of 19° East for the mean magnetic declination, with a range of 1° due to local attraction.</p> | |