

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES

OF THE

REHABILITATION OF THE CENTER 1/4 SECTION CORNER

OF SECTION 10

TOWNSHIP 31 SOUTH, RANGE 3 WEST,

OF THE WILLAMETTE MERIDIAN,

IN THE STATE OF OREGON.

EXECUTED BY

A. Bert Skeesick, Cadastral Surveyor

Robert H. Browning, Surveying Technician

Under Special Instructions dated July 13, 1979, approved July 17, 1979,
and Supplemental Special Instructions dated May 20, 1985,
approved May 24, 1985, which provided for the rehabilitation included
under Group No. 1000, and assignment instructions dated May 15, 2000.

Commenced September 25, 2000

Completed September 25, 2000

T. 31 S., R. 3 W., Willamette Meridian, Oregon

FEET	<p>The following field notes describe the rehabilitation of the center 1/4 section corner of section 10, township 31 south, range 3 west, Willamette Meridian, Oregon, as provided for in the Special Instructions dated July 13, 1979, and Supplemental Special Instructions dated May 20, 1985, under Group No. 1000, Oregon, "Rehabilitation of Corner Points, Without Remonumentation, When Suitable Monument Exists."</p> <p>The rehabilitation of the center 1/4 section corner of section 10 was for administrative purposes of the Bureau of Land Management.</p> <p>The mean magnetic declination as taken from U.S. Geological Survey quadrangle map "MILO, OREG.", Provisional Edition 1986, is 18° 30' East.</p>
	<p align="center">Rehabilitation of the Center 1/4 Section Corner of Section 10, T. 31 S., R. 3 W., Willamette Meridian, Oregon</p> <hr/> <p align="center">(Rehabilitating a corner established by John M. Jelley, Cadastral Surveyor, in 1964)</p> <hr/> <p>The center ¼ sec. cor. of sec. 10, monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.</p> <p align="center">T 31 S R 3 W</p> <p align="center">C¼ S 10</p> <p align="center">1964</p> <p>from which the remains of the original bearing trees</p> <p>A burnt stump, 15 ins. diam., bears S. 81° E., 27.1 ft. dist., no scribe marks visible.</p> <p>A burnt stump, 12 ins. diam., bears S. 13° W., 19.8 ft. dist., no scribe marks visible.</p> <p>and new accessories</p> <p>A stainless steel post, 28 ins. long, 2½ ins. diam., set 25 ins. in the ground for a reference monument, bears N. 39° E., 18.6 ft. dist., with brass cap mkd. RM T31S R3W C1/4 S10 18.6 FT TO COR 2000 and an arrow pointing to the corner.</p>

**Rehabilitation of the Center 1/4 Section Corner of Section 10,
T. 31 S., R. 3 W., Willamette Meridian, Oregon**

FEET	<p>A stainless steel post, 28 ins. long, 2½ ins. diam., set 26 ins. in the ground for a reference monument, bears N. 42½° W., 13.4 ft. dist., with brass cap mkd. RM T31S R3W C1/4 S10 13.4 FT TO COR 2000 and an arrow pointing to the corner.</p> <hr/>
------	---