

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES
OF THE
REHABILITATION OF
CERTAIN CORNER POINTS
ON THE SUBDIVISIONAL LINES,

TOWNSHIP 26 SOUTH, RANGE 2 WEST,
OF THE WILLAMETTE MERIDIAN,
IN THE STATE OF OREGON.

EXECUTED BY

Timothy J. Moore, Cadastral Surveyor

Robert H. Browning, Surveying Technician

Under Special Instructions dated February 22, 2002,
approved February 22, 2002, which
provided for the rehabilitation included under Group No. 2000,
and assignment instructions dated July 1, 2002.

Survey commenced July 1, 2002

Survey completed July 8, 2002

T. 26 S., R. 2 W., Willamette Meridian, Oregon

FEET

The following field notes describe the rehabilitation of certain corner points on the subdivisional lines, township 26 south, range 2 west, of the Willamette Meridian, Oregon, as provided for in the Special Instructions dated February 22, 2002, under Group No. 2000, Oregon.

The rehabilitation of certain corner points, was made at the request of the Roseburg District Manager, for the administrative purpose of the Bureau of Land Management.

Each new bearing tree has a 2½ inch x ¼ inch magnetic nail (Mag-Nail) driven at the base on the right side-center.

The mean magnetic declination as taken from U.S. Geological Survey Quadrangle Map "OLD FAIRVIEW", Provisional Edition, dated 1989, is 18° East.

**Rehabilitation of Certain Corner Points on
the Subdivisional Lines,
T. 26 S., R. 2 W., Willamette Meridian, Oregon**

(Rehabilitating a corner established by Fred Mensch,
U.S. Surveyor, in 1916-18, and perpetuated by Irving Zirpel, Jr.
and William W. Glenn, Cadastral Surveyors, in 1959)

Cor. No. 1, Tract 37, on the W. bdy. of sec. 15, monumented with an iron post, 1 in. diam., firmly set, projecting 8 ins. above ground, in a mound of stone, 3 ft. base to top, with brass cap mkd.

S 16	T 26 S
1	R 2 W
TR 37	S 15
1918	

from which the remains of an orig. bearing tree

A sawed and decayed fir stump, 25 ins. diam., bears S. 74° W., 33.0 ft. dist., with scribe marks R 37 visible on open blaze.

and the remains of bearing trees mkd. by Zirpel and Glenn

A cedar, 14 ins. diam., bears S. 59¼° W., 40.3 ft. dist., with a healed blaze. (Record, S. 62° W.)

Rehabilitation of Certain Corner Points on
the Subdivisional Lines,
T. 26 S., R. 2 W., Willamette Meridian, Oregon

FEET

A decayed fir stump, size indeterminate, bears N. 84° W., 22.4 ft. dist., alongside of which is the fir trunk, 8 ins. diam., with scribe marks AP S16 BT visible on open blaze.

and a new bearing tree

A fir, 7 ins. diam., bears N. 35° W., 18.7 ft. dist., mkd. AP S16 BT.

(Rehabilitating a corner established by Irving Zirpel, Jr.
and William W. Glenn, Cadastral Surveyors, in 1959)

The N 1/16 sec. cor. of sec. 15 only, monumented with an iron post, $2\frac{1}{2}$ ins. diam., firmly set, projecting 5 ins. above ground, with brass cap mkd.

| N 1/16
| S 15
1959

from which the remains of bearing trees mkd. by Zirpel and Glenn

A chinquapin snag, 26 ins. diam., bears N. $43\frac{1}{2}^{\circ}$ E., 17.8 ft. dist., with fragmentary scribe marks visible on partially healed blaze.

A pine, 29 ins. diam., bears S. $23\frac{3}{4}^{\circ}$ E., 63.4 ft. dist., with no marks visible.

and a new bearing tree

A fir, 8 ins. diam., bears N. $55\frac{1}{2}^{\circ}$ E., 16.4 ft. dist., mkd. N 1/16 S15 BT.
