

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES
OF THE
DEPENDENT RESURVEY OF PORTIONS OF THE SOUTH AND WEST BOUNDARIES,
AND SUBDIVISIONAL LINES,
AND THE SUBDIVISION OF SECTION 19,
TOWNSHIP 32 SOUTH, RANGE 1 WEST,
OF THE WILLAMETTE MERIDIAN,
IN THE STATE OF OREGON.

EXECUTED BY

Francis J. Simon, Cadastral Surveyor

Under Special Instructions dated February 11, 2002,
approved February 12, 2002, which provided for
the surveys included under Group No. 2007,
and Assignment Instructions dated March 13, 2002.

Survey commenced April 22, 2002

Survey completed June 26, 2002

T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET	<p>The following field notes are those of the dependent resurvey of portions of the south and west boundaries, and subdivisional lines, and the subdivision of section 19, township 32 south, range 1 west, Willamette Meridian, Oregon.</p> <p>The history of official surveys pertaining to this survey is as follows:</p> <p>The south boundary was surveyed by Nathaniel Ford, U.S. Deputy Surveyor, in 1856.</p> <p>The west boundary and subdivisional lines were surveyed by Rufus S. Moore, U.S. Deputy Surveyor, in 1883.</p> <p>A portion of the south boundary was resurveyed by Elmer F. Strickler, U.S. Surveyor, in 1917.</p> <p>A portion of the subdivisional lines were resurveyed and section 15 was subdivided by Hans W. Thielsen, Cartographer, (Cadastral), in 1955.</p> <p>A portion of the south boundary was resurveyed by Hans W. Thielsen, Cadastral Surveyor, in 1957. The plat was accepted in 1959 and subsequently suspended in 1969.</p> <p>Certain original corner points were remonumented by Joseph S. Gawron, Cadastral Surveyor, in 1966.</p> <p>A corrective dependent resurvey of Thielsen's 1957 resurvey was performed by John M. Jelley and Rollin D. Aanrud, Cadastral Surveyors, in 1969.</p> <p>A portion of the south boundary and subdivisional lines were resurveyed and section 32 was subdivided by Lynn M. Roseberry and Terrence O. Nickerson, in 1985.</p> <p>The survey was executed in accordance with the specifications set forth in the <u>Manual of Surveying Instructions, 1973</u>, and the Special Instructions dated February 11, 2002, for Group No. 2007, Oregon.</p> <p>The directions of the lines are based on the true meridian as determined by direct solar observations and were carried forward by means of sustained angulation. All measurements along the lines were derived through the use of electronic measuring equipment.</p> <p>An analysis of the unadjusted field data assured a closure not exceeding 1:4000 in error. Measured distances and</p>
------	---

T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET

directions have been adjusted by Cadastral Measurement Management for Windows (WinCMM), computer software that incorporates a least squares adjustment routine. The adjusted bearings and distances are reported to the nearest second and 0.01 foot.

Preliminary to the resurvey, the lines of the prior surveys were retraced and search was made for all corners and other calls of record. Identified corners were remonumented in their original positions. The retracement data were thoroughly verified and only the true line field notes are given herein.

Only those lines which represent Bureau of Land Management property lines were blazed, painted, and tagged with Bureau of Land Management boundary signs.

Each new bearing tree has a 2½ inch x ¼ inch magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

The geographic position (NAD 1927) of the center ¼ section corner of section 19 as determined by a tie to National Geodetic Survey Triangulation Station "DREW", is as follows:

Latitude: 42° 46' 28.95" N. Longitude: 122° 51' 45.49" W.

**Dependent Resurvey of a Portion of the South Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

(Restoring the 1856 survey by Nathaniel Ford, the 1883 survey by Rufus S. Moore, the 1917 resurvey by Elmer F. Strickler, the 1969 corrective dependent resurvey by John M. Jelley and Rollin D. Aanrud, and the 1985 resurvey by Lynn M. Roseberry and Terrence O. Nickerson)

Beginning at the cor. of secs. 3, 4, 33, and 34 monumented with an iron post, 2 ins. diam., firmly set, projecting 18 ins. above the ground, with brass cap mkd.

Dependent Resurvey of a Portion of the South Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET											
	<div style="text-align: center;"> <table border="1" style="margin: auto;"> <tr> <td>T 32 S</td> <td>R 1 W</td> </tr> <tr> <td>S 33</td> <td>S 34</td> </tr> <tr> <td>S 4</td> <td>S 3</td> </tr> <tr> <td colspan="2">T33S</td> </tr> <tr> <td colspan="2">1917</td> </tr> </table> </div> <p>from which the remains of the original bearing trees</p> <p style="padding-left: 40px;">A root hole, bears N. 55° E., 17.8 ft. dist., with decayed remains of a fir tree alongside, size indeterminate, with no marks visible.</p> <p style="padding-left: 40px;">A root hole, bears S. 75° E., 18.5 ft. dist., with decayed remains of a fir tree alongside, size indeterminate, with no marks visible.</p> <p style="padding-left: 40px;">A fir, 33 ins. diam., bears N. 70° W., 18.5 ft. dist., with a healed blaze.</p> <p>and a bearing tree mkd. by Strickler</p> <p style="padding-left: 40px;">A fir, 19 ins. diam., bears S. 59½° W., 37.0 ft. dist., with a healed blaze.</p> <p>and a bearing tree mkd. by person(s) unknown and reported by Lloyd R. Smith, Professional Land Surveyor No. 2011, in 1983, on recorded Survey No. 9731</p> <p style="padding-left: 40px;">A cedar, 10 ins. diam., bears N. 86½° E., 11.6 ft. dist., with a healed blaze.</p> <p>and a bearing tree mkd. by Smith</p> <p style="padding-left: 40px;">A cedar, 12 ins. diam., bears S. 67¾° E., 21.0 ft. dist., with scribe marks 33S R1W S3 visible on partially healed blaze.</p> <p>N. 88° 34' 46" W., bet. secs. 4 and 33.</p> <p>Descend NW. slope, through heavy timber and light undergrowth.</p>	T 32 S	R 1 W	S 33	S 34	S 4	S 3	T33S		1917	
T 32 S	R 1 W										
S 33	S 34										
S 4	S 3										
T33S											
1917											
245	Clear Creek, 2 ft. wide, course S. 45° W.										
2403.22	A point established by Larry J. Friar, Professional Land Surveyor No. 961, in 1981, recorded Survey No. 8840, and is accepted as a point on line; and designated a witness point, monumented with an iron rod, ½ in. diam., firmly set, projecting										

Dependent Resurvey of a Portion of the South Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEEET	<p>2 ins. above the ground, with a faded plastic cap mkd. FRIAR PLS 961, from which bearing trees mkd. by Friar</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S. 66° E., 11.6 ft. dist., with a healed double blaze.</p> <p style="padding-left: 40px;">A ponderosa pine, 10 ins. diam., bears S. 7¼° W., 4.0 ft. dist., with a healed double blaze.</p> <p>At the corner point</p> <p>Placed an aluminum cap directly over iron rod, mkd.</p> <div style="text-align: center; margin-left: 100px;"> WP S 33 <hr style="width: 50px; margin: 0 auto;"/> S 4 2002 </div>
2746.51	<p>The ¼ sec. cor. of secs. 4 and 33, perpetuated by the Jackson County Surveyor's Office in 1978, recorded in the County Rehabilitation Data Base; monumented with an iron post, 1½ ins. diam., firmly set, projecting 2 ins. above the ground, with brass cap mkd.</p> <div style="text-align: center; margin-left: 100px;"> JACKSON COUNTY 1978 T 32 S R 1 W 33 1/4S— 4 T 33 S </div> <p>from which an original bearing tree</p> <p style="padding-left: 40px;">A black oak, 12 ins. diam., bears N. 55° E., 27.1 ft. dist., with no marks visible on open decayed double blaze.</p> <p>and bearing trees mkd. by the County Surveyor's Office</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears S. 11¾° W., 48.5 ft. dist., with a healed double blaze.</p> <p style="padding-left: 40px;">A black oak, 7 ins. diam., bears N. 28° W., 31.5 ft. dist., with a healed double blaze.</p> <hr style="width: 200px; margin-left: 100px;"/> <p>N. 86° 02' 25" W., beginning new measurement.</p>

Dependent Resurvey of a Portion of the South Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET									
	Descend SW. slope, through scattered timber and light undergrowth.								
1090	Trail Creek, 10 ft. wide, course S. 35° E.								
1279.46	The W 1/16 sec. cor. of secs. 4 and 33, established by Larry J. Friar, Professional Land Surveyor No. 961, in 1981, recorded Survey No. 8840, and is accepted as the corner; monumented with an iron rod, 5/8 in. diam., firmly set, projecting 2 ins. above the ground, with a faded plastic cap mkd. FRIAR PLS 961, from which bearing trees mkd. by Friar								
	A fir, 8 ins. diam., bears S. 68½° W., 11.7 ft. dist., with a healed double blaze.								
	A fir, 8 ins. diam., bears N. 23¾° W., 8.6 ft. dist., with a healed double blaze.								
	At the corner point								
	Placed an aluminum cap directly over iron rod, mkd.								
	<div style="text-align: center;"> <table border="0"> <tr> <td></td> <td style="text-align: right;">S 33</td> </tr> <tr> <td style="text-align: right;">W 1/16</td> <td style="text-align: right;">_____</td> </tr> <tr> <td></td> <td style="text-align: right;">S 4</td> </tr> <tr> <td></td> <td style="text-align: right;">2002</td> </tr> </table> <hr style="width: 30%; margin: 10px auto;"/> </div>		S 33	W 1/16	_____		S 4		2002
	S 33								
W 1/16	_____								
	S 4								
	2002								
	N. 86° 02' 25" W., beginning new measurement.								
	Ascend E. slope, along N. edge of recently cut timber and S. edge of medium timber.								
710	East edge of pond, bears N. and S.								
780	West edge of same pond, bears N. and S.								
870	Center of Upper Trail Creek Road, 18 ft. wide, gravel surface, bears N. 15° W. and S. 15° E.								
1279.56	The cor. of secs. 4, 5, 32, and 33, monumented with an iron post, 2 ins. diam., firmly set, projecting 6 ins. above the ground, in a collar of stone, with brass cap mkd.								

**Dependent Resurvey of a Portion of the South Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET

T 32 S	R 1 W
S 32	S 33
S 5	S 4
T 33 S	
1957	

from which an original bearing tree

A black oak, 10 ins. diam., bears N. 85° W.,
33.7 ft. dist., with no marks visible on a rotted blaze.
(Record, 35.0 ft.)

and bearing trees mkd. by Thielsen

A fir, 21 ins. diam., bears N. 50° E., 79.9 ft. dist.,
with a healed blaze.

A sugar pine, 16 ins. diam., bears S. 38° W.,
95.0 ft. dist., with a healed blaze.

A ponderosa pine, 40 ins. diam., bears N. 31¼° W., 5.3 ft.
dist., with a healed blaze.

and a bearing tree mkd. by Roseberry and Nickerson

A fir, 14 ins. diam., bears S. 24° E., 32.3 ft. dist.,
with a healed blaze.

**Dependent Resurvey of a Portion of the West Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

(Restoring the 1883 survey by Rufus S. Moore)

From the cor. of secs. 19, 24, 25, and 30, perpetuated by the Jackson County Surveyor's Office, in 1964 and 1986, recorded in the County Rehabilitation Data Base; monumented with an iron post, 1½ ins. diam., firmly set, projecting 7 ins. above the ground, with brass cap mkd.

**Dependent Resurvey of a Portion of the West Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET	
	<p>From this point, a point established by Shaner and not utilized by this survey, bears N. 65° 00' 00" E., 0.97 ft. dist., monumented with an iron post, 2½ ins. diam., firmly set, projecting 18 ins. above the ground, with brass cap mkd. T.32S. R.1-2W. W.M. SEC. COR. S24 19 S25 30 1970 O.P.E. 4906 and a cross in the center.</p> <p>N. 0° 01' 51" E., bet. secs. 19 and 24.</p> <p>Ascend slight SE. slope, along E. bdy. of recently cut timber and W. bdy. of medium timber.</p>
663.02	<p>From this point, a point established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S File No. 63/148, bears West, 0.46 ft. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above the ground, with bronze cap mkd. RCE 6604. This point was established using erroneous control and is not utilized by this survey.</p>
1326.16	<p>Point for the S 1/16 sec. cor. of secs. 19 and 24. No permanent monument established.</p>
1372.68	<p>From this point, a point established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S File No. 63/148, bears West, 30.90 ft. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above the ground, with bronze cap mkd. RCE 6604. This point was established using erroneous control and is not utilized by this survey.</p>

**Dependent Resurvey of a Portion of the West Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET	
1988.46	<p>From this point, a point established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S. File No. 63/148, bears West, 26.73 ft. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 3 ins. above the ground, with bronze cap mkd. RCE 6604. This point was established using erroneous control and is not utilized by this survey.</p>
2652.32	<p>The ¼ sec. cor. of secs. 19 and 24, reestablished at proportionate measurement by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639 and Douglas County recorded Survey No. M56-69, utilized by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County Recorded Survey No. 7087, Douglas County recorded Survey No. M166-25 and C.S. File No. 63/148. There is no remaining evidence of the original corner; therefore this point and is accepted as the corner; monumented with an iron post, 2½ ins. diam., firmly set, projecting 3 ins. above the ground, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 32 S R 2 W R 1 W S 24 S 19 1/4 S 1976 LS 536</p> </div> <p>from which remains of bearing trees mkd. by Baughman</p> <p style="padding-left: 40px;">A cedar snag, 7 ins. diam., bears S. 2° E., 3.1 ft. dist., with scribe marks R1W 1/4 S19 and other illegible marks visible on partially healed blaze.</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N. 29° W., 18.4 ft. dist., with a healed double blaze.</p> <p>and a bearing tree mkd. by person(s) unknown</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears S. 47½° E., 19.9 ft. dist., with a healed double blaze.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 0° 04' 48" E., beginning new measurement.</p> <p>Ascend broken E. slope, through medium timber.</p>
2651.84	<p>The cor. of secs. 13, 18, 19, and 24, determined at Douglas County Surveyor record distances from an original bearing tree,</p>

**Dependent Resurvey of a Portion of the West Boundary,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET

2 county bearing trees, and a bearing tree mkd. by a private surveyor, from which an original bearing tree

A yew, 10 ins. diam., bears N. 45° E., 9.9 ft. dist., with scribe marks T32S R1W S and other illegible marks visible on partially healed blaze. (Record, N. 50° E.)

and bearing trees mkd. by the County Surveyor's Office, in 1963

A yew, 19 ins. diam., bears S. 46° E., 18.3 ft. dist., with scribe marks 32S R1W S19 CS BT visible on partially healed blaze.

A white fir, 23 ins. diam., bears N. 56° W., 82.7 ft. dist., with a healed blaze.

and a bearing tree mkd. by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639, Douglas County recorded Survey No. M56-69

A fir, 15 ins. diam., bears S. 70° W., 22.6 ft. dist., with a healed blaze.

The 1963 County Surveyor's monument is not recovered and the mound of stone is scattered.

At the corner point

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, in a collar of stone, with brass cap mkd.

T 32 S	
R 2 W	R 1 W
S 13	S 18
S 24	S 19
2002	

Deposit a magnet in a white plastic case at the base of the stainless steel post.

**Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

(Restoring the 1883 survey by Rufus S. Moore and
the 1955 resurvey by Hans W. Thielsen)

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEEET	<p style="text-align: center;">_____</p> <p>From the ¼ sec. cor. of secs. 19 and 30, perpetuated by the Jackson County Surveyor's Office in 1964, recorded in the County Rehabilitation Data Base; monumented with an iron post, 1½ ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.</p> <p style="text-align: center;">T 32 S R 1 W 19 1/4 ——— C.S. COR. 30</p> <p style="text-align: center;">1964</p> <p>from which the remains of an original bearing tree</p> <p style="padding-left: 40px;">A fir snag, 24 ins. diam., bears S. 32° W., 9.2 ft. dist., with illegible scribe marks visible on open blaze.</p> <p>and bearing trees mkd. by the County Surveyor's Office</p> <p style="padding-left: 40px;">A fir, 16 ins. diam., bears S. 70° W., 24.4 ft. dist., with a healed blaze.</p> <p style="padding-left: 40px;">A fir, 17 ins. diam., bears N. 47½° W., 34.3 ft. dist., with a healed blaze.</p> <p>N. 89° 24' 20" W., bet. secs. 19 and 30.</p> <p>Descend broken W. slope, through medium timber.</p>
1452.40	<p>The W 1/16 sec. cor. of secs. 19 and 30, established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S File No. 63/148, and is accepted as the corner; monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above the ground, with bronze cap mkd. RCE 6604.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over inverted iron post, with brass cap mkd.</p> <p style="text-align: center;">S 19 W 1/16 ——— S 30</p>

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEEET	<p style="text-align: center;">2002</p> <p>from which</p> <p style="padding-left: 40px;">A cedar, 10 ins. diam., bears N. 21° E., 15.7 ft. dist., mkd. W1/16 S19 BT.</p> <p style="padding-left: 40px;">A fir, 9 ins. diam., bears S. 60° W., 5.0 ft. dist., mkd. W1/16 S30 BT.</p> <p>Deposit a magnet in a white plastic case at the base of the stainless steel post.</p> <hr style="width: 30%; margin: 10px auto;"/> <p>N. 89° 16' 21" W., beginning new measurement.</p> <p>Descend SW. slope, through scattered timber.</p> <p>155 Oregon State Highway No. 227, asphalt surface, 21 ft. wide, bears N. 20° W. and S. 20° E.</p> <p>1199.51 The cor. of secs. 19, 24, 25, and 30, on the W. bdy. of the Tp.</p> <hr style="width: 30%; margin: 10px auto;"/> <p>From the cor. of secs. 17, 18, 19, and 20, monumented with an iron post, 2 ins. diam., firmly set, projecting 10 ins. above the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="border-collapse: collapse; margin: 0 auto;"> <tr> <td style="padding: 0 5px;">T 32 S</td> <td style="padding: 0 5px;">R 1 W</td> </tr> <tr> <td style="padding: 0 5px;">S 18</td> <td style="padding: 0 5px;">S 17</td> </tr> <tr> <td style="padding: 0 5px;">S 19</td> <td style="padding: 0 5px;">S 20</td> </tr> <tr> <td colspan="2" style="padding: 0 5px;">1955</td> </tr> </table> </div> <p>from which remains of the original bearing trees</p> <p style="padding-left: 40px;">A broken off fir snag, size indeterminate, bears S. 28° W., 10.6 ft. dist., with scribe marks W S19 visible on detached blaze.</p> <p style="padding-left: 40px;">A fir, 31 ins. diam., bears N. 75° W., 7.7 ft. dist., with scribe marks T3 S W visible on bark. (Record, 5.9 ft.)</p> <p>and bearing trees mkd. by Thielsen</p> <p style="padding-left: 40px;">A fir, 30 ins. diam., bears N. 14° E., 20.6 ft. dist., with a healed blaze. (Record, 19.8 ft.)</p>	T 32 S	R 1 W	S 18	S 17	S 19	S 20	1955	
T 32 S	R 1 W								
S 18	S 17								
S 19	S 20								
1955									

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET	
	<p>A fir, 32 ins. diam., bears S. 63½° E., 57.5 ft. dist., with a healed blaze. (Record, 58.7 ft.)</p> <p>A fir, 26 ins. diam., bears S. 54¼° W., 23.1 ft. dist., with a healed blaze.</p> <p>A fir, 29 ins. diam., bears N. 5° W., 37.0 ft. dist., with a healed blaze.</p> <p>and a bearing tree reported by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, recorded Survey No. 6639</p> <p>A fir, 31 ins. diam., bears S. 88° E., 43.2 ft. dist., with a bulldozer blade scar facing the cor.</p> <p>N. 89° 51' 53" W., bet. secs. 18 and 19.</p> <p>Descend NW. slope, through medium timber.</p>
2761.21	<p>The ¼ sec. cor. of secs. 18 and 19, reestablished at proportionate measurement by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639 and Douglas County recorded Survey No. M56-69. There is no remaining evidence of the original cor.; therefore this point is accepted as the cor.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 10 ins. above the ground, in a collar of stone, with brass cap mkd.</p> <div style="text-align: center;"> <p>T 32 S R 1 W</p> <p>S 18</p> <p>1/4 <u> </u></p> <p>S 19</p> <p>1976 LS536</p> </div> <p>from which bearing trees mkd. by Baughman</p> <p>A fir, 14 ins. diam., bears S. 65° E., 17.0 ft. dist., with a healed blaze.</p> <p>A ponderosa pine, 17 ins. diam., bears N. 46¾° W., 28.9 ft. dist., with a healed blaze.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 89° 51' 53" W., beginning new measurement.</p> <p>Ascend slight NE. slope through medium timber.</p>
2536.05	<p>The cor. of secs. 13, 18, 19, and 24, on the W. bdy. of the Tp.</p>

**Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET	
	<hr/> <p>Subdivision of Section 19, T. 32 S., R. 1 W., Willamette Meridian, Oregon</p> <hr/>
	<p>From the ¼ sec. cor. of secs. 19 and 30.</p> <p>N. 1° 12' 29" W., on the N. and S. centerline of sec. 19.</p> <p>Descend NW. slope, through medium timber.</p>
1349.39	<p>The center S 1/16 sec. cor. of sec. 19, established by Ken W. Hoffine, Professional Land Surveyor No. 2291, in 1995, Jackson County recorded Survey No. 14467, and is accepted as the corner; monumented with an iron rod, 5/8 in. diam., firmly set, projecting 4 ins. above the ground, with an aluminum cap mkd.</p> <p style="text-align: center;">LONEROCK TIMBER C S 1/16 S 19 C 1995 PLS2291</p> <p>from which bearing trees mkd. by Hoffine</p> <p style="padding-left: 40px;">A fir, 18 ins. diam., bears S. 68½° E., 29.4 ft. dist., with scribe marks S 19 BT and other illegible marks visible on partially healed blaze.</p> <p style="padding-left: 40px;">A fir, 17 ins. diam., bears S. 1 3/4° W., 12.6 ft. dist., with scribe marks CS 19 BT and other illegible marks visible on partially healed blaze.</p>
	<hr/> <p>N. 1° 12' 29" W., beginning new measurement.</p> <p>Ascend slight SW. slope, along E. edge of recently cut timber and W. edge of medium timber.</p>
1349.46	<p>The center ¼ sec. cor. of sec. 19, established by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639 and Douglas County recorded Survey No. M56-69, utilized by Ken W. Hoffine, Professional Land Surveyor No. 2291, in 1995, Jackson County recorded survey No. 14467, and is accepted as the corner; monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd.</p>

Subdivision of Section 19,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEEET	<p style="text-align: center;">T 32 S R 1 W C 1/4 + S 19 1976 OLS536</p> <p>from which remains of bearing trees mkd. by Baughman</p> <p style="padding-left: 40px;">A sawed fir stump, 12 ins. diam., bears S. 36° W., 19.6 ft. dist., with illegible scribe marks visible on a partially healed double blaze.</p> <p style="padding-left: 40px;">A sawed fir stump, 15 ins. diam., bears N. 19½° W., 18.1 ft. dist., with a healed double blaze.</p> <p>and new bearing trees</p> <p style="padding-left: 40px;">A fir, 15 ins. diam., bears N. 78½° E., 22.1 ft. dist., mkd. C1/4 S19 BT.</p> <p style="padding-left: 40px;">A white fir, 16 ins. diam., bears S. 12½° E., 36.9 ft. dist., mkd. C1/4 S19 BT.</p> <p>From this point, National Geodetic Survey triangulation station "DREW", bears N. 8° 34' 31" W., 35,062.33 feet distance (mean bearing and sea level distance), monumented with a brass tablet cemented in a concrete filled tile pipe, mkd. DREW 1993.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 1° 10' 03" W., beginning new measurement.</p> <p>Descend N. slope, along E. edge of recently cut timber and W. edge of medium timber.</p>
1315.66	<p>The center N 1/16 sec. cor., established by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639 and Douglas County recorded Survey No. M56-69, and is accepted as the corner; monumented with an iron post, 2½ ins. diam., firmly set, projecting 8 ins. above the ground, with brass cap mkd.</p> <p style="text-align: center;">T 32 S R 1 W C 1/16 N 1976 OLS536</p> <p>from which bearing trees mkd. by Baughman</p>

Subdivision of Section 19,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET	
1315.11	<p>A fir, 27 ins. diam., bears S. 76° E., 40.1 ft. dist., with a healed blaze.</p> <p>A fir, 15 ins. diam., bears N. 36° W., 30.6 ft. dist., with a healed blaze.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>N. 1° 08' 38" W., beginning new measurement.</p> <p>Ascend slight SE. slope, through medium timber.</p> <p>The ¼ sec. cor. of secs. 18 and 19.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>From the ¼ sec. cor. of secs. 19 and 20, perpetuated by the Douglas County Surveyor's Office, in 1968, recorded in C.S. File No. 54/71, monumented with an iron post, 1½ ins. diam., firmly set, projecting 9 ins. above the ground, with brass cap mkd.</p> <p style="text-align: center;">COUNTY SURVEYORS OFFICE T 32 S R 1 W ¼ S 19 S 20</p> <p style="text-align: center;">1968</p> <p>from which the remaining original bearing tree</p> <p style="padding-left: 40px;">A fir, 39 ins. diam., bears N. 80° E., 9.0 ft. dist., with scribe marks 1/4S BT visible on bark, a large X chop, and a healed blaze. (Record, 7.3 ft.)</p> <p>and a bearing tree mkd. by the County Surveyor's Office</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears N. 89° W., 7.3 ft. dist., with a healed double blaze.</p> <p>S. 89° 39' 16" W., on the E. and W. centerline of sec. 19.</p> <p>Descend W. slope, along N. bdy. of medium timber and S. bdy. of recently cut timber.</p>
2919.78	<p>The center ¼ sec. cor. of sec. 19.</p> <hr style="width: 20%; margin: 10px auto;"/> <p>S. 89° 38' 03" W., beginning new measurement.</p> <p>Ascend NE. slope, through recently cut timber.</p>

Subdivision of Section 19,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET	
1415.65	<p>The center W 1/16 sec. cor. of sec. 19, established by Glenn S. Baughman, Professional Land Surveyor No. 536, in 1976, Jackson County recorded Survey No. 6639 and Douglas County recorded Survey No. M56-69, utilized by Ken W. Hoffine, Professional Land Surveyor No. 2291, in 1995, Jackson County recorded survey No. 14467, and is accepted as the corner; monumented with an iron post, 2½ ins. diam., firmly set, projecting 4 ins. above the ground, in a collar of stone, with brass cap mkd.</p> <p style="text-align: center;">T32S R1W CW 1/16 <hr style="width: 10%; margin: auto;"/>S 19 1976 LS536</p> <p>from which bearing trees mkd. by Baughman</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears S. 5° W., 20.1 ft. dist., with a healed double blaze.</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears N. 11° W., 6.4 ft. dist., with a healed double blaze.</p> <hr style="width: 20%; margin: 20px auto;"/> <p>S. 89° 40' 45" W., beginning new measurement.</p> <p>Ascend E. slope, through medium timber.</p>
1177.50	<p>The ¼ sec. cor. of secs. 19 and 24, on the W. bdy. of the Tp.</p> <hr style="width: 60%; margin: 10px auto;"/> <p>From the W 1/16 sec. cor. of secs. 19 and 30.</p> <p>N. 0° 22' 00" W., on the N. and S. centerline of the SW¼ of sec. 19.</p> <p>Ascend SW. slope, through medium timber.</p>
668.35	<p>From this point, a point established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S File No. 63/148, bears West, 1.00 ft. dist., monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above the ground, with bronze cap mkd. RCE 6604. This point is not utilized in this survey.</p>

**Subdivision of Section 19,
T. 32 S., R. 1 W., Willamette Meridian, Oregon**

FEET	
1336.88	<p>The SW 1/16 sec. cor. of sec. 19, established by Jack L. Brewen, Registered Professional Engineer No. 6604, in 1977, Jackson County recorded Survey No. 7087, Douglas County recorded Survey No. M116-25 and C.S File No. 63/148, utilized by Ken W. Hoffine, Professional Land Surveyor No. 2291, in 1995, Jackson County recorded Survey No. 14467, and is accepted as the corner; monumented with an iron post, 1 in. diam., firmly set, projecting 6 ins. above the ground, with bronze cap mkd. RCE 6604, from which bearing trees mkd. by Hoffine</p> <p style="padding-left: 40px;">A fir, 21 ins. diam., bears N. 45¼° E., 10.4 ft. dist., with a healed blaze.</p> <p style="padding-left: 40px;">A fir, 32 ins. diam., bears S. 76½° W., 39.0 ft. dist., with a healed blaze.</p> <p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, directly over inverted iron post, with brass cap mkd.</p> <p style="text-align: center;">SW 1/16 S 19 2002</p> <p>Deposit a magnet in a white plastic case at the base of the stainless steel post.</p> <hr/> <p>S. 89° 53' 13" E., on the E. and W. centerline of the SW¼ of sec. 19.</p> <p>Ascend NW. slope, through medium timber.</p>
400	<p>Spur, slopes S., descend SE. slope along N. edge of medium timber and S. edge of recently cut timber.</p>
1432.49	<p>The center S 1/16 sec. cor. of sec. 19.</p> <hr/> <p style="text-align: center;">GENERAL DESCRIPTION</p> <p>The lands surveyed are located approximately eight miles north of the town of Shady Cove, Oregon, in both Douglas and Jackson Counties. Access is gained by way of Oregon State Highway No. 227, Jackson County Road No. 501, and several roads maintained by the United States Bureau of Land Management and</p>

Subdivision of Section 19,
T. 32 S., R. 1 W., Willamette Meridian, Oregon

FEET	<p>United States Forest Service. Elevation is approximately 2000 to 3400 feet above sea level.</p> <p>The soil in the area is composed generally of rocky clay. The area is drained by Clear Creek, Elk Creek, Trail Creek, and Wall Creek. Timber consists primarily of cedar, fir and pine. Undergrowth varies from light to dense.</p> <p>There were no mineral deposits or mining activity noted along the lines surveyed. There is one residence in section 19. No springs were noted. The land is primarily used for timber production.</p> <p>The mean magnetic declination, as shown on United States Geological Survey 7½ minute quadrangle map "RAGSDALE BUTTE, OREGON," Provisional Edition, dated 1989, is 18° East.</p>
------	--