

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES
OF THE
REMONUMENTATION OF
THE CORNER OF SECTIONS 22, 23, 26, AND 27

**TOWNSHIP 21 SOUTH, RANGE 4 WEST,
OF THE WILLAMETTE MERIDIAN,
IN THE STATE OF OREGON.**

EXECUTED BY

A. Bert Skeesick, Cadastral Surveyor

Robert H. Browning, Surveying Technician

Under Special Instructions dated February 22, 2002,
approved February 22, 2002, which provided for the surveys included
under Group No. 2000, and Assignment Instructions dated November 16, 2006.

Survey commenced November 22, 2006

Survey completed November 22, 2006

T. 21 S., R. 4 W., Willamette Meridian, Oregon

The following field notes describe the remonumentation of the corner of sections 22, 23, 26, and 27, Township 21 South, Range 4 West, Willamette Meridian, Oregon, as provided for in the Special Instructions dated February 22, 2002, under Group No. 2000, Oregon.

The remonumentation of this section corner was made at the request of the Roseburg District Manager for the administrative purposes of the Bureau of Land Management.

Each new bearing tree has a 2½ inch x ¼ inch magnetic nail (Mag-Nail) driven at the base on right side center, unless otherwise noted in the corner description.

The mean magnetic declination, as taken from U.S. Geological Survey quadrangle map "CURTIN, OREG.", Provisional Edition, dated 1987, is 19° East.

**Re monumentation of the Corner of Sections 22, 23, 26, and 27,
T. 21 S., R. 4 W., Willamette Meridian, Oregon**

(Re monumenting a corner established by Harvey Gordon and Charles T. Gardner, U.S. Deputy Surveyors, in 1855-56, and remonumented by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, in 1980-81)

The cor. of secs. 22, 23, 26, and 27, determined at record bearing and dist. from the remains of bearing trees mkd. by Jelley and Rogers

- A sawed decayed fir stump, 13 ins. diam., bears N. 1° E., 24.1 ft. dist., with no marks visible.
- A fir, 35 ins. diam., bears S. 32¼° E., 44.2 ft. dist., with a healed blaze. (Record, S. 36° E.)
- A fir snag, 11 ins. diam., bears S. 55° W., 16.5 ft. dist., with a healed blaze. (Record, S. 50½° W.)
- A sawed decayed fir stump, 7 ins. diam., bears N. 36° W., 27.1 ft. dist., with fragmentary scribe marks visible on a partially healed blaze.

From which the remains of the original bearing trees

- A roothole bears S. 57° E., 37.1 ft. dist., with no trunk visible. (Record, S. 55° E., 35.0 ft.)
- A sawed decayed fir stump, 39 ins. diam., bears S. 82¼° W., 32.9 ft. dist., with no marks visible. (Record, S. 78° W., 29.0 ft.)

(Note: The iron post set by Jelley and Rogers in 1980 was located lying loose on the ground, on top of a scattered mound of stone.)

At the cor. point

Reset the iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

Remonumentation of the Corner of Sections 22, 23, 26 and 27,
T. 21 S., R. 4 W., Willamette Meridian, Oregon

T21S	R4W
S22	S23
<hr/>	
S27	S26

1980

from which new bearing trees

A fir, 28 ins. diam., bears N. $28\frac{1}{4}^{\circ}$ E., 29.8 ft. dist., mkd.
T21S R4W S23 BT

A fir, 25 ins. diam., bears S. $69\frac{1}{2}^{\circ}$ W., 15.4 ft. dist.,
mkd. T21S R4W S27 BT

A cedar, 30 ins. diam., bears N. $57\frac{1}{4}^{\circ}$ W., 20.1 ft. dist.,
mkd. T21S R4W S22 BT