

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

FIELD NOTES
OF THE
THE REHABILITATION OF THE
S 1/16 SECTION CORNER
BETWEEN SECTIONS 9 AND 10

TOWNSHIP 30 SOUTH, RANGE 5 WEST,
OF THE WILLAMETTE MERIDIAN,
IN THE STATE OF OREGON.

EXECUTED BY

Timothy J. Moore, Cadastral Surveyor

Robert H. Browning, Surveying Technician

Under Special Instructions dated February 22, 2002,
approved February 22, 2002, which provided for the surveys included
under Group No. 2000, and Assignment Instructions dated November 29, 2005.

Survey commenced November 29, 2005

Survey completed November 29, 2005

T. 30 S., R. 5 W., Willamette Meridian, Oregon

The following field notes describe the rehabilitation of the S 1/16 section corner of sections 9 and 10, Township 30 south, Range 5 West, of the Willamette Meridian, Oregon, as provided for in the Special Instructions dated February 22, 2002, under Group No. 2000.

The rehabilitation of the S 1/16 section corner of sections 9 and 10, was made at the request of the Roseburg District Manager, for the administrative purpose of the Bureau of Land Management.

Each new bearing tree has a 2½ inch X ¼ inch magnetic nail (Mag-Nail) driven at level elevation with the monument right side-center.

The mean magnetic declination as taken from the U.S. Geological Survey Quadrangle map, "CANYONVILLE, OREG.", Provisional Edition, dated 1986, is 18½° East.

**Rehabilitation of the S 1/16 Section Corner of Sections 9 and 10,
T. 28 S., R. 8 W., Willamette Meridian, Oregon**

Rehabilitating a corner established by Lynn M. Roseberry
and James Jelley, Cadastral Surveyors, in 1969,

The S 1/16 sec. cor. of secs. 9 and 10, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd.

S 1/16
S 9 | S 10
1969

from which the bearing trees mkd. by Lynn M. Roseberry and James E. Jelley, Cadastral Surveyors, in 1969

A fir, 18 ins. diam., bears S. 14½° E., 35.0 ft. dist., with a healed blaze.

A fir, 24 ins. diam., bears N. 56½° W., 19.1 ft. dist., with a healed blaze.

and new bearing trees

A fir, 16 ins. diam., bears N. 61½° E., 59.9 ft. dist., mkd. S 1/16 S10 BT.

A fir, 12 ins. diam., bears S. 68½° E., 66.2 ft. dist., mkd. S 1/16 S10 BT.

Corner is located West, 15 ft. dist., of a ridge, bears S. 25° E. and N. 40° W. (Record cor. is on top of ridge and bears N. 20° W. and S. 20° E.)

This corner is located in an area where the timber is about to be harvested. The bearing trees marked in 1969 will likely be fell, therefore new bearing trees have been marked to perpetuate the corner position.
