

F.C. Inman Dep.
Co. Surveyor
Wit. G. D. Chapman
Wit. G. B. Fargle
Aug. 18-1919

1/4 Cor. between Secs 24 & 25 - Renewed as per old
B.T.s by setting a 3" x 36" Fir Stake from which
a 40" B. Oak Bro. N. 82 1/4° W. - 1.17 ch.
a 12" W. " " S. 3 3/4° W. - 1.40 " (see page 58)

1/4 Cor. bet Secs. 26-27.

Renewed corner from Original B 9 N 0° 15' E
no trace of other B 9

Set 1/2" x 1 1/2" Iron bar marked new tree
An Oak 14" S 89° W 683 ft.

J. W. Cole Deputy
L. H. Smith }
Cred. Comm.

Cor. to Secs 22-23-26-27

Renewed Cor from original B 9 N 30° W 160 ± ft

Mark. new tree a B Oak 24" dia N 39° 15' E 221 ±

Meander Cor. of South Umpqua River on line
bet 22 & 23.

Set an oak post 4" x 4" x 40" also iron bar 1/2" x 1 1/2" x 36"
mark. new trees A Maple 36" dia S 43° W 7 ft
A B Oak 15" S 78° E 197 ft.

G. G. Stewart Dep. Nov. 14-21
J. S. Germond.
H. F. Roeder
M. E. Richardson

Cor. to 29-30-31-32

Put Iron Pipe for Cor. Cor. was pile rocks placed
by J. S. Germond around original stake which had burned off.

Marked new tree. 30" Fir N 34° E 59 ± ft
12" Alder S. 75° 30' E 47.0 ft
10" Maple S 50° W 5.7 ft
10" Maple N 38° W 9 ± ft.

Original trees destroyed by fire

G. G. Stewart, Deputy
J. S. Germond
H. F. Roeder
M. E. Richardson

1/4 Cor. bet 29-30. Decayed stake and one B.T. found. Put

1" Eye bar for corner. New B.T. Marked. 74" Fir S 43° W 35 links
18" Fir (original) N 45° E 57 links

G. G. Stewart, Deputy
H. F. Roeder

Geo G. Stovacek

18 75 10 7 3

E. Q. Stewart, Deputy
H. F. Poeder
A. E. Richardson
Frank Gummel
Otto Moore
near 16-31

1/4 Cor. bet 29 and 32. Found 6" Laurel, ant eaten and dying.
had been scribed. other B.T. gone. Found 6" Fir, had been
blazed for corner, but no scribe marks. Marked fir "1/4 sec Cor"
marked new B.T. 10" Fir S 70° E 35² ft.
24" Fir N 86° E 17² ft. (Ren. #9)

Geo G. Strasser
Ed Mosher
Arman Strasser
K. Emmett
(Ren. #10)

1/4 Cor. bet. Secs. 8-9
Renewed corner from original bearing trees
which are standing but nearly dead.
Set a 1 1/2 x 24 inch pipe and a 4x4x30 Cedar
post from which old B.T.s 30" Oak S 10° E 191⁴ ft.
a 15" Oak scribed bears S 1° 30' W 334
Marked new trees W Oak 12" N 47° 00' E 119⁵ ft.
" " " " 16 S 64° 15' W 81⁸ ft.

Dec 18-22 1923
W. Cole - Surveyor
(Ren. #11)
(Ren. #12)

Witness Corner to 1/4 Sec. Corner bet 7+8.
Made a mound of rock 49³ ft. North
of 1/4 Cor. as 1/4 Corner came in River.
Corner was renewed from the old B.T.
both of which were standing but no marks
were visible. Marked new trees
a Myrtle 10" S 69° 00' W 13² marked W @ CS B.T.
" " " S 75° 30' E 23³ " " " "
Corner to Secs. 4-5-8-9
Renewed corner from 4 Original B.T.s
Set a 3/4 x 30 Iron pin from which
Original B.T. Oak bearing scars N 70° E 193² ^{meas.} Horizontal
" " " " scribe S 1° 30' E 277 slope meas
" " " " " S 5° W 237² " "
" " " " " down N 87° W 1011⁷ ft.
A Boulder marked with X S 36° E 50 ft
Corner in middle of spur leading up main
ridge