

F.C. Fiear Dep. Co. Surv.
Tom Hart J. Whit.
J.C. Haegi
#1 March 22-1919

✓ Cor. of D.L.C.'s 43-44-45 - I reset from old B.D. B.T. stumps which Tom Hart & G.W. Short claim is the Original B.T. they having seen the marks on same. Later M.B. Germond C.D. Claims also to have seen the original letters on the stumps 8 or 9 years ago. I set a 1" x 48" I. Rod for the Corner from which the 24" B.D. Stump Bns. N. 63° - E. 3.53 Ch - remarked a 16" Laurel Bns. N. 86 1/2° E. 4.04 Ch. marked C.S.B.T.

G.G. Stewart, D.C.S.

✓ #2 N.W. Cor. Cl 48.

Renewed this corner from the original B.9. which bears scribe marks but is dead. Set at the tree N 5° E 64 lbs and set and oak post also and iron bolt 1" x 14" from which I mark new trees. A B Oak 24" dia S 54 W 45 ft. A B Oak 12" dia S 17° 30' E 72 ft.

Ben B. Johnson

J.W. Cole Deputy
May & June 1924

✓ #3 J.W. Cor. 48

A Rock 6" x 8" x 12" from which a W Oak 30" dia bears N 66° 30' E 58 ft. This Rock had been placed for cor. by some previous surveyor. but no record made

✓ #4 Cor. bet. 17 & 18

Set oak post also an iron P.P. Spike from which the original B.9. N 10° E 238 ft. bearing scribe marks. marked new trees

#4 A B Oak 18" dia S 40° 30' W 35 ft.
A " " 14" dia N 73° W 24 ft.

✓ ✓ Cor to Sec 7-8-17-18

Set oak stake from which the remains of original B.9. check with field notes marked new trees. A Fir 18" dia S 29° W 39 ft. A fir 24" S 56° 10' E 36 ft. A Fir N 33° 40' E 36 ft. A fir 59° W 45 ft.

#5

26-5

G.G. Stewart, D.C.S.
Sept 24 1922

Tom Dixon, Charles Crocker witnesses
Vol. 3 Pg 124

✓ S.W. corner D.L.C. #41; I reset from old B.T.S. standing but rotten. Set 3/4" g.I.P. Mark. 20" B.O. S41 1/2° E 52 ft
8" B.O. N41 1/2° E 48 ft. J.H. Short & Tom Dixon witness

✓ E. corner D.L.C. #41. I reestablish by running South and East lines of D.L.C. 41. B.T.s gone. Set I.P. mark
#7 8" W.O. N64° W 66 ft. 12" B.O. N67° E 62 ft. Var 17° East. Vol. 3 Pg 124

✓ N.E. corner D.L.C. #41. I reset from old B.T.S. set Iron pipe mark a 24" B.O. N51° E 52 ft. 24" B.O. S70° W 107 ft (old B.T.)

Deputy County Surveyor
Mar. 18 1929

R.R. Richardson - E.H. Harger
A Smith witness

✓ 1/4 Section Corner between Secs 7 & 12 T26S R54E W
Position identified from one O.B.T. scribe marks nearly rotted off. Drive 2" x 3/8" iron pipe
14" Fir S42° W 84 lks. Scribed 1/4 S 12 CSBT
#9 12" 10" " N31 1/2° E 36 " " 1/4 S 7 CSBT

✓ S.W. Cor. Calvin C. Reed D.L.C. 47 (F.B. 36 Page 4)
Oak 24" N. 1° W. 37 Feet
#10 " 10" N. 19° W. 21 1/2 "
" 6" S. 54° W. 11 1/2 "

✓ S.E. Cor. D.L.C. 47 (F.B. 36 Page 7)
Ash 12" N. 36° E. 14 1/2 Feet
#11 Maple 14" S. 70° E. 11 8 "

✓ S.E. Cor. John Akin D.L.C. 51 (F.B. 36 Page 5¹⁵)
B. Oak 14" S. 88 3/4° W. 40 8 Feet
#12 W. " 18" N. 41 1/2° W. 30 0 "

✓ 1/4 S. Cor. Bet. Secs. 29 & 32 (F.B. 36 Page 21)
Fir 12" S. 55° E. 22 2 Feet
" 12" N. 66 1/2° E. 25 9 "
#13 Laurel 8" N. 47° W. 6 8 "

✓ 1/4 S. Cor. Bet. Secs. 20 & 29 (F.B. 36 Page 23)
4" Oak post
#14 Laurel 8" N 60 1/2° W 19 2 Feet
Fir 20" N 83° E 18 3 " (over)