

E. Summers
Dep. Co. Surveyor
Feb. 1920
Wit. Wm. McClanahan
Johnston

May 6. 1915

✓ 1/4 Sec Cor bet Secs 25-26

Rock set for Cor. from which original
tree S 25° W 93 li mark new tree
BO 6 in dia N 20° E 21 li
" " 6 " " S 53 W 20 "

#1

✓ 1/4 Sec. Cor. bet. Secs 31 & 32

Set a Blue Limestone ^{6"x18"} marked 1/4 D from wh.
a W. Oak 9" bears S. 87° 45' W. 4.22 ch.
#2 a B. Oak. 36" " N. 25° 15' W. 6.05 ch. Old. B. T.

✓ Meander Corner on South Annapqua River

Between Secs. 31 & 32 - On Rt. bank of River

Re-set 8 chains North of 1/4 Sec. Corner

by setting a Limestone ^{6"x18"} from which
a B. Oak 24" Brs. S. 22 1/2° W. 1.35 chs
#3 a W. Oak 9" " S. 22° E. 0.94 chs.

J.W. Cole Deputy #115/21
L.A. Smick
Sherman Marks

✓ NE Corner of Fitzhugh D.L.C. No 40

I renewed this corner from two original B Ts which
are alive and standing and bearing scars
but do not correspond with the Govt files nor
an old record of Mr Thiels says these trees were
marked by the U S Surveyor. I renewed cor.
by setting and iron pipe 1"x30" also an oak
post. from which the trees bear as follows

a W Oak 15" dia bears N 69° 30' W 27.7 ft.
#4 a B Oak. 26" " " S 38° 15' W 14.5 ft.

✓ Cor to Secs. 20-21-28-29

I renewed this corner from the original

Bearing trees which bear as follows

a 48" B Oak standing and bearing scibe marks bears S 71° 30' E 80.5 ft
a 30" W Oak " " " S 53° 30' W 130
a snag of a B Oak bearing scars N 80° 45' W 154
#5 a Large Oak down bearing scars N 85° E 108
set iron pipe and oak post 4'x4'x36"

✓ 1/4 Cor. bet. Secs 20 + 21 Renewed. this corner from original Bearing trees a W Oak S 83 1/2 E 186 ft. a W oak down decayed N 55 W 178 ft.

Set 4" x 4" x 40" oak post. and marked a new tree

#6 a W Oak 10" dia S 12 30 W 33 ft.

✓ Cor. to 16 + 17. - 20 - 21

Renewed this corner from the rotting remains of the original B.T.s one of which Mr James Cooper testifies that he had seen scribe marks on several years previous. The remains of the trees checked for direction and distances given in the field notes I set an iron pin 1/2" x 36" and

#7 marked new trees a W Oak 20" dia N 42 15 E 122 3/4
" " 30" dia N 17 50 W 224 2

✓ S. N. Cor. of Cl. 61. Renewed this corner from the original Bearing tree which was alive and standing and which I chopped open and found the scribe marks I set an oak post for cor and marked new trees

A B Oak 30" dia S 16 15 W 162 5 ft

a W " 30" " N 19 W 157 1/2 "

#8 A Rock 8" x 10" x 12" marked Cl 61 bears N 88 E 2 ft

✓ 1/4 Corner. North Bay Section 20.

Renewed this corner from the original Bearing trees set a 4" x 4" x 40" oak post from which the original Bearing trees bear

#9 as follows S 57 E 9.9 ft.

N 17 E 30 ft.

✓ NW Cor. of Cl 43. I set an iron pipe and an

oak post from which a W oak 12" dia bearing scars but no scribe marks visible on account of

decay. bears S 83 E 52 6 ft. a W oak 18" dia

#10 dead showing no marks bears S 37 W 4.7 ft.

also and on paper of W Cole Deputy
set by John Watters
Feb. 1824

80 5/4
W 131 9
W 154 8
80