

U.S. G. M.: Survey Dept. Co. Surveyor  
P.D. Wolfbein } Witnesses  
S.K. Bowden }

Nov. 1922

✓ Cor. to Secs. 17-18-19 and 20  
I renewed this cor from one original B.T. which was alive and in which the scribe marks were visible. Set an Oak Post 4" x 4" x 20" and marked trees as follows - 2" Pipe  
W.O. 24" in dia. bears N 19° 0' E 17 Lks.  
B.O. 20" " " " S 72° 0' E 50 ft.  
# 2 W.O. 16" " " " S 56° 45' W. 49 ft.  
B.O. 18" " " " N 59° 30' W. 89 ft.

C.W. Spryng Dep. C.S.  
Feb 1923  
Bergth claim  
Olley Barn Substn  
Gleicher Patterson

✓ 1/4 Sec to Sec. 2 & 3 #3  
Pointed rock set in ground. Orig. B.T.s rotted away. I check to poles where they stood and remark new B.T.s. A. B. Oak 9" in dia 121.5 lks.  
P. W. Oak 4" in dia S 34° 15' E 31 lks.

Sam Whitcomb  
H.L. Eppertson

✓ 1/4 Cor between Sec 5-32 South Boundary.  
✓ I set corner from Old Oak tree which was standing and in good shape. Old ash B.T. in evidence but down I marked a 15" Alder for other B.T. which bears S 28° W 559 lks

#5  
#6  
W.H. Wondo  
Survey No 3-28  
Nov. 16-1925  
W.S. Grear } Witnesses  
A.B. Hatfield }  
L.S. Patterson }

✓ 1/4 Cor. Bet. 15-16 Old B.T.s good - Set new stake  
✓ 1/4 Cor Bet. 10-15 ✓ ✓ ✓ ✓  
✓ Cor. Sec. 9-10-15-16  
Find Old B.T.s Stump N 56 1/4 W. 520 scars visible  
" " " Oak S 40 3/4 E 4.00  
" " " Oak S 30 1/4 E 1.90 given as 4.90  
# 1 Mark Oak 12" N 69° 30' W 51 lks B.T. 59 C.S.

Ben B. Irving D.C.S.J.  
J. E. Eppertson Corer

28-5

T. J. Eppstein, Corner  
Bill Bolan, witness  
S. W. Whitcomb, witness  
#8  
May 10-1926

✓  
Cor to Sec 4-5-32-33 T<sup>285</sup> T<sup>295</sup> R 5W  
I renewed this Corner from 3 old B.T.,  
other tree gone. Set Oak Post.  
Fence Post at corner. Old B.T. are  
badly rotten. Marked New B.T.  
20" B.O. S 66 W 170 <sup>7</sup>/<sub>16</sub> B.O. 14" N 28-30 W ~~178~~<sup>688</sup> feet  
10" W O N 78 E 148 <sup>8</sup>/<sub>16</sub>; B O 10" S 24 E 120 feet

Ben B Irving D.C.S. Jan 6  
Wit N.E. Richardson 1938  
Blinn Cooper #9  
Westey French  
Frank Bohme

✓  
1/4 Cor bet Sec. 22 + 23. <sup>set</sup> with 10" x 14" x 20" sandstone.  
from Original B.T. { Laurel 24" Dia., bears N 50° E 32.1 Ks  
Fir 38" " " S 60° W 35.1 Ks.  
Chiseled 1/4 S.C.S. on S. Face of sandstone. The Laurel  
was 32 links distance, instead of 23 links. Remark  
Old Bearing Trees.

✓  
Cor. of section 14, 15, 22, & 23.  
Location determined from 12" Black Oak. Original  
Bearing Tree. N 35° W 45 Ks. which we Chopped out.  
Scribe marks plain & legible. Tree fell due to its weight being  
all <sup>on</sup> one side. A black oak rotten stump N 17° E 34 Ks with hole  
where ~~B.T.~~ Original blazes were, was another Orig. B.T.  
Other B.T. destroyed but evidences of stump & roots  
checked location for Bearing & distance

#10  
Set as sandstone 8" x 10" x 16", 12" in ground for Cor.  
From which Fir 12" N. 12 E, 44.1 Ks; Fir 10" S 41° E 24 Ks.  
Fir 12" S 86 W, 23 Ks; Fir 14" N 36° W 60-1 Ks.

✓  
CORNER 146 Range 5 & 6 North West Cor. Sec. 6.  
Corner was set from old B.Ts. by driving 3/4" x 36"

#11A  
Round Iron Bolt 30" in Ground. New Bearing Trees  
was Marked as Follows { 18" BIK Oak, Bears S 62°-15' E 152.6 Ft.  
14" " " " S 86°-20' W 226.6 Ft.

✓  
1/4 CORNER NORTHSIDE SEC. 6  
Set from one original B.T. by driving 3/4" x 36" round  
Iron Bolt in Ground. Marked New Bearing Trees  
as Follows { 14" Fir Bears S 22°-15' E 120.3 Feet  
8" White Oak " S 46°-45' W 17.3 Feet