T 28 S R 7 W.

✓ ✓ #40 NE corner of Coats D.L.C # 59.
Renewed from the original B.T which is alive and standing but scribe marks were rotted out. I remarked the tree and set an iron pipe 1" x 30 pipe as per field notes.

~~~~~~~~~~~~~~~~~~~~~~~~~~~

✓ ✓ #41 N W Corner of Coats D.L.C # 59
Set on E line of Lathrope Cl. and [illegible] a distance of 9.00 Chs North of S.E Cor. of Lathrope Cl. Set a large rock for corner marked. Cl. 59 C.S.

✓ #42 ✓ 1/4 Cor. bet. Sections 30 + 31. could not find trees given in Govt field notes but found stake in fence corner from which trees bearing scars indicating bearing trees as follows.

A. B. Oak.	30" dia	N 9° 00' W	83.0 ft.
" " "	30" "	S 62° E	19 "
" " "	46" "	N 42° 30 E	69.4 "
" " "	24" "	S 22° W.	32.5 "

J W Cole. Co. Surveyor Feb. 1923

W H Coats
E Richardson
H Bergh
Witnesses

✓ Hathorne's Cor. to Twps 28 and 29 S. Rgs 7 and 8 W.
Set a cedar post from which
A. W Oak 16" bearing old scribe marks bears N. 0° 30 E 168.9 ft. An original B.T ~~x~~ A B Oak which has chopped open chips show scribe marks N 5° 00 W 222.6 ft.
✓ A. B Oak original B.T showing scars, and alive and standing bears S 27° 00 W 463.6 ft.
#43 An oak stump bears S 76 3/4 E I did not measure this distance I marked an 8" W Oak N 87° 30' E 11.0 ft. marked C S B.T.
~~~~~~~~~~~~~~~~~~~~~~~~~~~

T 28 S R 7 W.

JWCole Co Sur.
Feb 1903
Wit. { W.H Coats
E Richardson
A Bright

#44 Hathornes 1/4 Cor W side Sec 31.
Set from original B Ts, Laurel was nearly rotted away so I marked a new tree. An 18" fir S 80½°E $27^{\underline{6}}$
Set iron pipe 1"x24" for cor also maple post. 3"x3"x36"

Same Witnesses →

#45 Corner to Secs 31-32-5-6
Set a flat rock erected mound of rock marked with a + with a Rock on top bearing old mark S T
Flat rock 6"x12"x18" from which Original BTs Laurel with scribe marks rotted off. N. 30°E $16^{\underline{5}}$ ft.
Laurel bearing old scribe marks N15W $66^{\underline{0}}$ ft.
Fir B T bearing scars which I did not open bears S75°E $12^{\underline{0}}$ ft.
Original oak B. T. down and decaying bears S43°W. $28^{\underline{4}}$ ft.
Corner as set by Gordon Steuart bears N85°30'W $36^{\underline{7}}$ ft.

J W Cole Co. Surveyor

#46 1/4 S boundary of Sec 31.
Could find no evidence of the Original B Ts I determined the original position of this corner from tie given in field notes of the McCulloch D.L.C also by testimony of W H Coats who claimed that he had been told by Tom McCulloch that he had dug out witness trees while preparing the ground for a garden. Also the tie given by the field notes of the Twp line to the creek checked within a few feet. The old fence line built on the Survey for the W side of Thomas Coats Cl. if continued would