

Jan 23 1924  
J. W. Cole  
B. B. Drury  
Cohn

bears N 6° 30' E 239 ft  
A 24" B Oak alive bearing scars  
N 78° W 153 ft. A stump of 40" B Oak  
in which I found old face with scribe  
mark B, bears S 60° W 126 ft.  
marked a boulder 4' x 8' x 4' N 36° E 52 ft.  
A 12" W Oak N 47° W 20 ft  
A 8" W Oak S 19° 15' W 36 ft

I renewed the NW corner of the Riddle  
D.L.C No 39 from original B.T.

I set a sandstone 8x10x15 marked C.L. 39  
; C.B. from which stump of original B.T.  
with scribe marks visible N 3° E 258 ft.

A B Oak 26 nearly dead bears N 82° E 54°  
blazes face westerly, top blaze chopped  
out but old wood bearing scribe marks  
were found in the hollow of the tree when  
we chopped open the lower blaze.

I also found a portion of scribe marks  
below. This corner does not correspond  
with all calls of the field notes but I  
could find no position that would fulfill  
all calls. I marked new trees

W Oak 10' S 49° 30' E 45 ft  
" " " S 52° 30' W 39 ft

Corner of 20-21-28+29  
I renew corner from one O.B.T. a hane still  
standing & scribe mark Plain I marked new  
Bearing Trees as follows:

Fir 12" Bears S 13° E 22 ft  
Larrel 5" " S 70° W 10 ft  
" 6" " N 14° E 18 ft

July 14 1928  
H. A. Eppstein  
Cohn  
with Clifford Fidd  
J. W. Cole  
B. B. Drury

30-6

Replaced by Ben B Irving Dep. Co. Surveyor April and May 1929 (Survey of Marks & wallenberg)  
 Witnesses - N.R. Richardson - Allen Moore.  
 Note:- The records of corner descriptions of the Public Survey Office at Portland does not agree with corners as found on ground. Remainder of field notes check reasonably close. After consultation with Dist. Attorney and Co. Surveyor and in view of the fact that no corners in field checked records and that age of corners corresponded with original work it was decided to use field corners as the true corners and they were renewed accordingly. R.R.S.

✓ 1/4 Corner North side Sec 1  
 Set on ~~the~~ North line of section 1 and in position to bear out facing of an Orig BT.  
 Drove a 3/4" x 3/6" Gal Pipe from which  
 a white oak 16" dia bears N 15° 38' W 84 lks blazed & scribed 1/4 5 BT (Orig BT)  
 " 8 " " N 86° 12' W 71 " " " 1/4 5 36 CS BT.

✓ Section Corner  $\frac{35}{21}$ / $\frac{36}{1}$   
 Position identified by 4 orig BTs and hole filled with rotten wood as part of orig. stake. Set 5" x 60" post (fir) in mound of rock, Original BT's  
 Black oak 17" dia N 47° 17' E 91 lks.  
 " 8 " 520° 11' E 46 lks } Dead and rotting orig scribe marks OK.  
 Pine 36" N 27° 19' W 56 lks  
 " 30 534° 20' W 41 lks.

Replaced Oak BTs - Fir 12" dia N 75° 28' E 12 lks. Blazed and scribed T 29 S R 6 W 536 CS BT  
 Fir 13 " 538° 20' E 9 " " " T 30 S R 6 W 51 CS BT.

✓ Section Cor  $\frac{21}{11}$ / $\frac{12}{12}$   
 From facing of 2 orig. BTs drove a 3/4" x 3/6" Gal Pipe in a mound of Rock, Original BTs.  
 Pine 24" dia bears 585° E 117 lks  
 " 24" " " N 50° E 38 lks.  
 New BTs Fir 10" dia bears 50° 50' W 47 lks. blazed and scribed T 30 S R 6 W 511 CS BT  
 " 14 " " N 85° W 39 " " " T 30 S R 6 W 52 CS BT

✓ 1/4 Cor Sec. 11/12  
 Note. See W.F. Briggs survey in Vol. 00-Page 113-119 Dec. 9<sup>th</sup> 1873, For this Corner. By Eppstein.  
 Set from an old post in fence corner as best evidence available for location. This is on N and S line and fits location described in original field notes. Drove 3/4" x 3/6" Gal Pipe from which  
 a Cedar 12" dia bears S 15° W 89 lks blazed and scribed 1/4 5 11 CS BT  
 " 10" " " S 54° E 82 " " " 1/4 5 12 CS BT.