31-2

Jan-12-21 1931 — Barr & Downing Dep. Co. Surveyor.
NE Richardson
By Larson
F.L. Thomas

Witnesses

Sec. Cor $\frac{13}{24}\frac{18}{19}$ T31S R14W.

Position identified from OBT oak N77°W 114 lks and stump of pine N40°E 82 lks. Original notes call for 2 ash BTs. one is oak mentioned above and other must have been an oak as there has never been ash on spur.

Set Rock 6"x10"x18"-16" in ground for corner.
14" B. Oak N 42°E 131 lks T31SR1W S18 CSBT
20" " N65½°W 67 lks T31SR2W S13 CSBT
20" Madrona S 56°W 27 lks. T31SR2W S24 CSBT
18" Fir S10°E 150 lks. T31SR1E S19 CSBT

"

Sec. Cor. $\frac{12}{13}\frac{7}{18}$

Position identified from 1 OBT 20"W oak S57°E 87 lks which I remark T31SR1W S18 CSBT

Bloze 4 sides and scribe a 4" W. Oak for corner
T31SBT on NE — R1W S18 on SE
R2W S13 on SW - S12 CS on NW faces.

Set a Sandstone 3"x6"x14"-14" in ground along side
8" W. Oak S42°W 13 lks mkd T31SR2W S13 CSBT
10" Pine N55°W 63 " T31SR2W S12 CSBT
6" W Oak N28°E 18 " T31SR1W S7 CSBT

"

1/4 Sec Cor 13-18

Position identified ~~from~~ by proportional distances between Sec corners. Checked with holes where probable OBTs stood. Fire had burned all traces of original Corner.

Set a Sandstone 8"x8"x18" long-14" in ground. mkd 1/4
10" Fir N32°E 91 lks 1/4 S18 CSBT
14" " N32°W 74 lks 1/4 S13 CSBT

Jim Mayhew
Chas. Patterson
Joe Bennett
1902

C.E. Roberts

1/4 Cor. Bet. Secs. 14 & 15 (F.B. No. 6 Page 92)

Fir 18" N. 68½° W. 8 lks.

See Pg 169 for T31-3