

✓ Corner to Secs 22-23 26-27

Renewed this corner from three of the Original B.P.s which were standing bearing scribe marks. By using slope measure to the various trees the measurements given in the field notes correspond closely and the directions check very closely with those given in the field notes. Using a Magnetic Var of  $19^{\circ}30'E$

I set a 1 inch by 40 inch drill steel for the corner and marked new trees as follows

A. Fir 20 in dia  $S76^{\circ}30'W$  77.8 ft.

A. Fir 40 " "  $N45^{\circ}15'W$  58.0 ft

A. Fir 18 in dia  $N59^{\circ}45'W$  68.5 ft.

1/4 Corner on the North Side Sec. 26.

Renewed this corner by proportional measurement as I could find no evidence of the original corner.

I set a one by forty inch drill steel and a fir post from which a Ledge Rock marked 1/4 S, C.S, B.O. which bears  $S64^{\circ}00'W70^{\circ}$  and a fir tree 36 in dia marked with two notches on the East and West faces. stands 14 ft west of the corner.

✓ Corner of Sections 23-24-25-26.

Renewed the corner of 7 from the Original B.P.s which checked with field notes. I set a rock mound and a one inch drill steel 40 inches long for corner

J.W. Cole - Surveyor  
L.H. Billing } Witnesses,  
J.E. Revore }  
J.L. Johnson }

Feb. 1924